



Long Range Facilities Timeline- Descriptors

<u>Source</u>	
Campus Initials	i.e., RAE - Alexander Elementary
M&O	Maintenance & Operations
2006	2006 Bond first request
2010	2010 Bond first request
2014B	Completed within 2014 Bond
2017B	Completed within 2017 Bond
Food Ser	Nutrition & Food Service
East Tran	East Transportation
FCP	Facilities, Planning, and Construction
W Tran	West Transportation
<u>Planning Period</u>	
1	May 2021 bond
2	3 -5 years
3	within 10 years
2014B	Completed within 2014 Bond
2017B	Completed within 2017 Bond
Under Review	Further review required before action is taken
WO	Maintenance Work Order
GOF	General Operating Fund
Campus	Campus Needs to Address
FFE	Part of the retrofit cycle for furniture
HARVEY	Work part of Hurricane Harvey funding
<u>Rationale</u>	
A	Architectural
AG	Athletic Grounds
BE	Building Envelope - roof, exterior wall, windows
BI	Building Integrity - envelope as well as structural
C	Curriculum
G	Grounds
E	Electrical
IAQ	Indoor Air Quality
K	Kitchen/Food Service
LS	Life Safety (fire alarm)
M	Mechanical
M&O	Maintenance & Operation Item
O	Operations
P	Programming
RC	Replacement Cycle
SS	Safety & Security
T	Technology

Long Range Facilities Plan Timeline

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Agricultural Sciences Center	Support	Phase 2 expansion:		2014 Bond	G
Agricultural Sciences Center	Support	Outdoor Pavilion		2014 Bond	P
Agricultural Sciences Center	Support	Multi Purpose Show Arena		2014 Bond	P
Agricultural Sciences Center	Support	Project Center Building		2014 Bond	P
Agricultural Sciences Center	Support	Multi Purpose Covered Outdoor Arena		2014 Bond	P
Agricultural Sciences Center	Support	Eco Pond/Detention Pond		2014 Bond	BI
Alexander Elementary	ELEM	Roof replacement	M&O	2014B	RC
Alexander Elementary	ELEM	Replacement of generator, fire alarm & clocks which will address campus comment regarding clocks need to be working and synced throughout the building.	RAE & M&O	2017B	RC
Alexander Elementary	ELEM	Provide for locked casework in all rooms.	2010	2	P
Alexander Elementary	ELEM	Provide for more of a curved ramp to get large equipment on stage.	2010	2	P
Alexander Elementary	ELEM	Reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	2010	2	P
Alexander Elementary	ELEM	Original campus design provided for PE dressing rooms. Campus requested that they be renovated as storage space and creating a hall access doorway. Renovate art rooms. This building plan does not provide a space for a teachers lounge, we currently use storage space.	RAE	2	P
Alexander Elementary	ELEM	There are too few teacher restrooms - provide for additional staff restrooms.	RAE	2	P
Alexander Elementary	ELEM	Upgrades to teacher lounge and planning spaces	RAE	2	P
Alexander Elementary	ELEM	Upgrade clinic	RAE	2	P
Alexander Elementary	ELEM	Install a dimmer switch on stage lighting.	RAE	2	BI
Alexander Elementary	ELEM	Upgrade to library/learning centers	RAE	2	P
Alexander Elementary	ELEM	Traffic Safety- create additional car-rider stacking space on site to reduce the impact on public streets and make it safer for students who walk to get to and home from school.	Emergency Management	1	SS
Alexander Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors. Front office staff members have no way of knowing who is coming through the door.They need a monitoring system that shows what the cameras are seeing.	Emergency Management	2017B	SS
Alexander Elementary	ELEM	Additional Science Lab and multi-purpose room (we do not have an LGI)	RAE	2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Alexander Elementary	ELEM	Audio/ Visual System	RAE	2	RC
Alexander Elementary	ELEM	updated playground equipment	RAE	2017B	P
Alexander Elementary	ELEM	additional covered area on playground	RAE	GOF	P
Alexander Elementary	ELEM	Drainage issues on field of school yard, trenches that span the width and puddles throughout. Lack of grass causes hard surfaces which is unsafe for kids to run on as well as it is too sandy and results in muddy conditions when rainy.	RAE	GOF	BI
Alexander Elementary	ELEM	Need more lighting in front of building	RAE	2017B	SS
Alexander Elementary	ELEM	extreme temperatures in classrooms adjacent to exterior walls as well as many portables	RAE	2017B	E
Alexander Elementary	ELEM	Principals office at very front of building next to front entrance/corridor has extreme temperatures, need to wear gloves and layers to work at computer, sweating in summer	RAE	2017B	E
Alexander Elementary	ELEM	not enough storage space for PE equipment	RAE	2	P
Alexander Elementary	ELEM	need sound proofing as music rooms are adjacent to classrooms	RAE	2	P
Alexander Elementary	ELEM	Replacement of walk-in cooler freezer.	Food Ser	2	RC
Alexander Elementary	ELEM	add cold/ frost tops/ice cream units add water spouts to fill serving lines	Food Ser	2	P
Alexander Elementary	ELEM	open up serving line to storefront	Food Ser	2	P
Alexander Elementary	ELEM	Upgrade serving lines - add cold/frost tops/ ice cream units - add water spouts to fill serving lines Upgrade to Katy ISD standards.Meet menu and health dept. requirements	Food Ser	2	P
Alexander Elementary	ELEM	open up serving line to storefront- upgrade to Katy ISD standards. Increase participation- meet customer needs	Food Ser	2	P
Alexander Elementary	ELEM	upgrade line reach in warmers/coolers-upgrade to Katy ISD standards. Meet menu and health dept requirements.	Food Ser	2	RC
Bear Creek Elementary	ELEM	Additional lighting and cameras needed due to continued vandalism outside.	BCE	1	SS
Bear Creek Elementary	ELEM	Playground has no shade structure.	BCE	2014B	SS
Bear Creek Elementary	ELEM	The building in general has older electrical system and may need upgrading in the future	BCE	2	BI
Bear Creek Elementary	ELEM	Replace asphalt with concrete for both parking lots	BCE	2017B	BI
Bear Creek Elementary	ELEM	Carpet Replacement	M&O	2	RC
Bear Creek Elementary	ELEM	Additional power receptacles-2 duplex per room	2010	2	BI

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Bear Creek Elementary	ELEM	Music Rooms- need storage, shelves, books on floor	2010	2	P
Bear Creek Elementary	ELEM	Additional classrooms	BCE	2	P
Bear Creek Elementary	ELEM	Fine Arts- 2 music teachers are sharing 1 room- need additional music room	Fine Arts	2	P
Bear Creek Elementary	ELEM	Reconfigure Teacher Workroom and Lounge	M&O	2	p
Bear Creek Elementary	ELEM	Traffic Study- modify the site to create a ring road across the back (northwest) side of the playground leading around and into the north parking lot. This road should be large enough to allow double stacking cars.	Emergency Management	2017B	G
Bear Creek Elementary	ELEM	Flood Mitigation- the front and northeast sides of the buildings are less sloped than are the southeast and northwest sides. The northwest side during the recent event was inundated longer and is where there is current evidence of facility damage. The southeast side is more severely sloped and in a longer period of inundation are more likely to see soil liquification	Emergency Management	GOF	BI
Bear Creek Elementary	ELEM	Security- install or modify doors from the main (outside cafeteria and gym) hall into the classroom areas with access control to isolate classrooms from intruders. Three sets of doors identified as needed for this.	Emergency Management	2017B	SS
Bear Creek Elementary	ELEM	Science lab up to district standard- having a full time science facilitator	BCE	2	P
Bear Creek Elementary	ELEM	Additional lights on field/playground due to continued vandalism and trespassing	BCE	2017B	SS
Bear Creek Elementary	ELEM	West wing parking lot- additional staff needed to park	BCE	2017B	G
Bear Creek Elementary	ELEM	No parking signs at walker intersection- many more walkers due to long car line	BCE	2017B	SS
Bear Creek Elementary	ELEM	Cracks in walls, especially the wall between the building and the portables	BCE	GOF	BI
Bear Creek Elementary	ELEM	Hallways around library are very dark and need better lighting. Also, we were told since a light fixture fell at Hutsell, our fixtures would need to be replaced since they are the same. We would like nice light fixtures that aren't just typical, flat, rectangular fluorescent lights	BCE	2	E

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Bear Creek Elementary	ELEM	While exterior of our school looks wonderful since being remodeled almost 10 years ago, the interior requires a lot to be to current district standards. We need lighter paint colors to get rid of the peeling wall paper, to remove the 1978 laminate and just bring the interior into the 21st century.	BCE	2	RC
Bear Creek Elementary	ELEM	Cafeteria - new sound pads above windows	BCE	2	BI
Bear Creek Elementary	ELEM	Our gym is still very dark and could use renovated lighting	BCE	2	E
Beck Junior High	JH	Additional department storage	BJH	2	P
Beck Junior High	JH	Front entry is extremely dark	BJH	2017B	SS
Beck Junior High	JH	Locker replacement- both in hallways and in the girls and boys locker rooms	Athletics	2	RC
Beck Junior High	JH	Scoreboard replacement for both gyms	Athletics	2	RC
Beck Junior High	JH	Lighting in hallways needs to be revamped to make it brighter. It is very dark.	BJH	2017B	RC
Beck Junior High	JH	Roof replacement	M&O	1	RC
Beck Junior High	JH	Sound system update in competition gym.	2010	3	RC
Beck Junior High	JH	Shelving or cabinets need to be installed in the larger closet in the practice gym. Current storage is inadequate and equipment often flows over into spaces which are against fire code due to lack of space.	BJH	2	P
Beck Junior High	JH	No speakers in hallways so if staff or students are in the hall and not in an actual classroom they miss the announcement.	BJH	2	P
Beck Junior High	JH	Weightroom expansion - knock out shower wall in Girls Athletics Locker room- inadequate space for athletics and storage	Athletics	2	G
Beck Junior High	JH	Replace athletic lockers	Athletics	2	RC
Beck Junior High	JH	Replace bleachers in gyms	Athletics	1	RC
Beck Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	2	
Beck Junior High	JH	Tennis court resurface	Athletics	2017B	RC
Beck Junior High	JH	We need more science lab space. With curriculum requirements, science labs are the norm and are done all of the time. Regular classrooms cannot accommodate the labs and there are no sinks.	BJH	2	P
Beck Junior High	JH	We would like water bottle fill stations. Perhaps we could have paired drinking fountains and water bottle fill stations so students would have an option.	BJH	2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Beck Junior High	JH	Front drive needs to be expanded. When buses or cars pull to our front curb, no one can get out of parking spaces.	BJH	2	
Beck Junior High	JH	We are in desperate need of a locker room update for both boys and girls. The shower areas need to be smaller and changing area made larger. We also need updated lockers.	BJH	2	P/RC
Beck Junior High	JH	The ensemble room for band and orchestra is way too small. It needs to be larger to accommodate the kids and instruments.	BJH	2	P
Beck Junior High	JH	We need additional custodial closets due to fire code. The fire marshal recently visited and two closets the custodians were using to store larger cleaning equipment and supplies are no longer allowed to be used according to the current firemarshal.	BJH		SS
Beck Junior High	JH	Walk-in cooler/freezer replacement. Consider Food Service comment: Increase freezer and cooler sizes and improve lighting	Food Ser	1	RC
Beck Junior High	JH	Renovate snack bar area	Food Ser	2	P
Beck Junior High	JH	Relocate dish machine to make more room for lines in the front. Redesign to fit more space for serving lines	Food Ser	2	P
Beck Junior High	JH	New equipment- ovens, steamers, dish machine	Food Ser	1	RC
Beck Junior High	JH	Remove unused/old equipment- Tilt skillet, stove top	Food Ser	1	P
Beck Junior High	JH	Larger storage area- increase in paper goods/food items needed to be stored	Food Ser	2	P
Beck Junior High	JH	Additional storage in manager office. Increase in paperwork required to store for documentation of national school breakfast/lunch program	Food Ser	2	P
Beck Junior High	JH	Renovation of kitchen area	Food Ser	2	RC
Beck Junior High	JH	Interior lighting upgrade	BJH	2	RC
Beck Junior High	JH	Need for additional science classrooms	BJH	2	P
Beck Junior High	JH	New student desks	BJH	2	P
Beckendorff Junior High	JH	Gym lighting retrofit.	M&O	2017B	E
Beckendorff Junior High	JH	Walk-in cooler freezer replacement.	Food Ser	3	RC
Beckendorff Junior High	JH	Replace carpet.	2010	2017B	RC
Beckendorff Junior High	JH	Gearboss system for athletic storage.	Athletics	3	P
Beckendorff Junior High	JH	New flat top lockers for both boys and girls.	Athletics	3	RC
Beckendorff Junior High	JH	8th grade science lab.	BDJH	3	P
Beckendorff Junior High	JH	Concrete surface for outside of competition gym- this area is a mud pit	Weightroom Expansion	3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Beckendorff Junior High	JH	Replace belachers in gym	Athletics	1	RC
Beckendorff Junior High	JH	Replacement scoreboards	Athletics	2017B	RC
Beckendorff Junior High	JH	Replace sound system in gym/ competition facilities	Athletics	2017B	RC
Beckendorff Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	3	P
Beckendorff Junior High	JH	Tennis court resurface	Athletics	2	RC
Beckendorff Junior High	JH	Band hall and orchestra expansion including storage	BDJH	3	P
Beckendorff Junior High	JH	Boys and girls locker room expansion due to enrollment	BDJH	3	G
Beckendorff Junior High	JH	Athletics- water fountains	BDJH	3	P
Bethke Elementary	ELEM	Additional lighting is needed in the Art Rooms	CBE	GOF	P
Bethke Elementary	ELEM	Curb markings for traffic - no stopping or standing	CBE	GOF	SS
Cardiff Junior High	JH	Security cameras are inadequate for monitoring all of the essential locations throughout and around the exterior of the building.	CJH	2017B	SS
Cardiff Junior High	JH	Gearboss system for athletic storage.	Athletics	3	P
Cardiff Junior High	JH	Several areas around the exterior of the building are dark and need additional lighting.	CJH	3	SS
Cardiff Junior High	JH	Carpet replacement.	M&O	2	RC
Cardiff Junior High	JH	Covered area outside of weight room- a covered area would provide more space for weight room activities	Weightroom Expansion	3	P
Cardiff Junior High	JH	Covered walkway from gyms to bus loading area-safety/weather	Athletics	3	SS
Cardiff Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	3	P
Cardiff Junior High	JH	Tennis court resurface	Athletics	2017B	RC
Cardiff Junior High		We would like to have doors placed on the entries to the cafeteria off of the main hallway like other junior highs have. This will allow us to block out noise during events in the cafeteria.	CJH	3	P
Cardiff Junior High		We would like to have a roll-up garage door on the exterior wall in the weight room. This would allow the coaches easier access to the outside where they have athletes doing many of the activities.	CJH	3	P
Central Maintenance	OPER	Additional Covered Storage along north fence line	M&O	2	
Central Maintenance	OPER	Carpet replacement.	M&O	2014B	RC
Cimarron Elementary	ELEM	Playground equipment is outdated and not all of it is under shade to protect students from extreme heat. In addition, the playground is not secure from community members (gate has no lock), the basketball courts are overgrown with weeds growing through cracked concrete, track is uneven and causing students to trip and fall	CE	2014B	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Cinco Ranch High School	HS	Two additional science lab classrooms.	CRHS	1	P
Cinco Ranch High School	HS	Additional computer labs	CRHS	2	P
Cinco Ranch High School	HS	Replace walk-in cooler/freezer.	Food Ser	1	RC
Cinco Ranch High School	HS	Replace chillers.	M&O	2017B	RC
Cinco Ranch High School	HS	Walk in Floral Cooler	CTE	2017B	P
Cinco Ranch High School	HS	Re-roof.	M&O	1	RC
Cinco Ranch High School	HS	Resurface track.	Athletics	2	RC
Cinco Ranch High School	HS	Fine Arts Department - add spout to fill water bottles throughout the building.	CRHS	1	P
Cinco Ranch High School	HS	The Fine Arts Department (choir, orchestra, theatre) can use additional space for large items or uniforms. The Fine Arts Department could use a large group workroom similar to what other departments have. The music department could use an additional instructional room for choir classes, ap theory, large group rehearsal, it could be added on to the end of the art room at the end of the 1100 hallway. Currently we are using a t-building, but scheduling is limited and the space is not good for singing.	CRHS	1	P
Cinco Ranch High School	HS	Fire alarm system - replace old/non functioning sensors.	CRHS	2017B	RC
Cinco Ranch High School	HS	Softball dugouts (2)- age of fixture & safety	Athletics	2017B	RC
Cinco Ranch High School	HS	Softball backstop- age of fixture & safety	Athletics	2017B	RC
Cinco Ranch High School	HS	Gain back storage room that was lost when girl locker room was put in- female wrestlers are being moved into locker room vacated by girls track. need the storage room for mats currently placed in school hallway when not in use.	Athletics	1	P
Cinco Ranch High School	HS	Small building with restrooms and possibly storage- there are no restrooms close by for the use of the kids. The swimming pool is the closest area. Outdoor storage would help in the staging of class and play as well. Room 1702D.	Athletics	1	P
Cinco Ranch High School	HS	Resurface the floors in the individual locker rooms- Safety Issue. Floors have gotten smooth over the years.	Athletics	1	RC
Cinco Ranch High School	HS	Repair and/or upgrade shower and toilet areas- 17 eyars of wear and tear on the facility.	Athletics	1	RC
Cinco Ranch High School	HS	Repair cracks in the floor & walls in the locker rooms- 17 years of wear and tear on the facility.	Athletics	GOF	BI
Cinco Ranch High School	HS	Paint the interior walls in all athletics areas- 17 years of wear and tear on the walls is showing.	Athletics	GOF	RC
Cinco Ranch High School	HS	Replace athletic lockers	Athletics	1	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Cinco Ranch High School	HS	Irrigation system update- all grass practice fields, baseball and softball. Convert all irrigation systems from "2 core" to "conventional wiring system". Cost would be \$35,000-40,000 per campus.	Athletics	2017B	
Cinco Ranch High School	HS	Replace bleacher in gyms	Athletics	1	RC
Cinco Ranch High School	HS	8 new natatorium starting blocks	Athletics	2017B	P
Cinco Ranch High School	HS	Tennis court resurface	Athletics	2017B	RC
Cinco Ranch High School	HS	Softball new backstop competition field netting- foul balls are landing on people's head in the bleachers and surrounding areas.	Athletics	2017B	
Cinco Ranch High School	HS	Pool- change track lighting to LIGHTRUSS	Athletics	2017B	
Cinco Ranch High School	HS	Re-turf the competition field.	Athletics	2017B	RC
Cinco Ranch High School	HS	Kitchen renovation		1	
Cinco Ranch Junior High	JH	Resurface track.	Athletics	2	RC
Cinco Ranch Junior High	JH	Hallways need paint and patching. Our entry floor is still tile which requires waxing. Prefer the surface that the newer buildings have in their entries	CRJH	GOF	BI
Cinco Ranch Junior High	JH	Expanded/new weight room and locker replacement	Athletics	2	G
Cinco Ranch Junior High	JH	Library- add a security system to help secure materials	CRJH	2	P
Cinco Ranch Junior High	JH	Library-add a sound system/speakers for making presentations	CRJH	2	P
Cinco Ranch Junior High	JH	Library- additional electrical needed all over the library	CRJH	2	P
Cinco Ranch Junior High	JH	Walk-in cooler/freezer replacement	Food Ser	2017B	RC
Cinco Ranch Junior High	JH	Scoreboard replacements	Athletics	2017B	RC
Cinco Ranch Junior High	JH	Roof replacement.	M&O	2	RC
Cinco Ranch Junior High	JH	Clocks are analog. The systems are very outdated	CRJH	2017B	RC
Cinco Ranch Junior High	JH	Fine Arts/Art- replace open shelves with deep drawers and add doors to cabinets	CRJH/Fine Arts	3	P
Cinco Ranch Junior High	JH	Fine Arts/Art- sinks are too shallow and need to be replaced with deeper ones with splash back.	CRJH/Fine Arts	2	P
Cinco Ranch Junior High	JH	Fine Arts/Art- if our rooms were pushed out (enlarged) that would be double awesome	Fine Arts	2	P
Cinco Ranch Junior High	JH	Fine Arts/Art- larger kiln room or closed closet to store glazes to upgrade to current standards	Fine Arts	2	P
Cinco Ranch Junior High	JH	Storage renovation- install Gearboss, create more space with better storage system and expansion	Athletics	2	P
Cinco Ranch Junior High	JH	Replace bleachers in gyms	Athletics	2	RC
Cinco Ranch Junior High	JH	Replace athletic lockers	Athletics	2	RC
Cinco Ranch Junior High	JH	Replace sound system in gym/competition facilities	Athletics	2017B	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Cinco Ranch Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	2	
Cinco Ranch Junior High	JH	Weightroom expansion - safety issue- girls locker room expansion- facility too small for the number of athletes in the program	Athletics	2	G
Cinco Ranch Junior High	JH	Water source in rooms 133,141,143,145 as well as hard floors. Consistently need 9 classrooms for science so these four have been converted. Water is required for labs and additional classrooms	CRJH	2	P
Cinco Ranch Junior High	JH	Add a 5 classroom wing to accommodate the newcomer program	CRJH	2	G
Cinco Ranch Junior High	JH	Water bottle refill station	CRJH	2	P
		Updated stage lighting			
Cinco Ranch Junior High	JH	Remove snack bar windows- able to serve more students in open concept serving lines, upgrade to current KISD standards	Food Ser	2017B	P
Cinco Ranch Junior High	JH	Remove snack bar drawers- no longer needed if we have serving lines	Food Ser	2017B	P
Cinco Ranch Junior High	JH	Relocate dish machine to make more room for lines in the front. Redesign to fit more space for serving lines	Food Ser	2017B	P
Cinco Ranch Junior High	JH	New equipment- ovens, steamers, dish machine	Food Ser	2017B	RC
Cinco Ranch Junior High	JH	Remove unused/old equipment- Tilt skillet, stove top	Food Ser	2017B	RC
Cinco Ranch Junior High	JH	Larger storage area- increase in paper goods/food items needed to be stored	Food Ser	2017B	P
Cinco Ranch Junior High	JH	Expand cooler and freezer- increase in menu items served to customers	Food Ser	2017B	P
Cinco Ranch Junior High	JH	Additional storage in manager office. Increase in paperwork required to store for documentation of national school breakfast/lunch program	Food Ser	2017B	P
Jeanne Coleman Support Annex	Support	Sound panels in commons area	JCSA	2	P
Jeanne Coleman Support Annex	Support	Additional sinks to clean play equipment	JCSA	2	P
Creech Elementary	ELEM	Need additional security cameras to increase visibility and security of all campus locations (at entrance of each grade level hallway, outside the library facing the main hallway, and additional camera in gym)	SCE	HH	SS
Creech Elementary	ELEM	Library- add 3 outlets to the library	SCE	GOF	P
Creech Elementary	ELEM	Library- build bookshelves on the weall beside the little room and on the wall next to the computer lab. This will house the Kindergarted book bags and paperback books.	SCE	HH	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Creech Elementary	ELEM	Library- build out the desktop for the computer wall so the last computer is on a sturdy top and not a rolling cart	SCE	HH	P
Creech Elementary	ELEM	Library- build out the shelves in the Everybody section and remove the temporary bookshelves	SCE	HH	P
Creech Elementary	ELEM	Library- remove benches and sitting area in the Everybody section and replace with more colorful casual seating	SCE	HH	P
Creech Elementary	ELEM	Chiller replacement	M&O	2017B	RC
Creech Elementary	ELEM	Roof replacement	M&O	2017B	RC
Creech Elementary	ELEM	Basketball pavillion needs repainting	SCE	3	RC
Creech Elementary	ELEM	Walk in cooler/freezer replacement	M&O	HH	RC
Creech Elementary	ELEM	Reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	2010	HH	P
Creech Elementary	ELEM	Renovate art rooms		HH	P
Creech Elementary	ELEM	Add cabinets to coaches office for PE storage	SCE	HH	P
Creech Elementary	ELEM	Restrooms- all need new mirrors, especially student restrooms	SCE	HH	RC
Creech Elementary	ELEM	Tinted film recommended on specific windows	SCE	HH	BI
Creech Elementary	ELEM	Add sink with water fountain to Room 9	SCE	HH	BI
Creech Elementary	ELEM	Need key locks installed on interior of restrooms by cafeteria(security in event of lockdown, doors cannot currently be locked)	SCE	HH	SS
Creech Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors.	Emergency Management	HH	SS
Creech Elementary	ELEM	Make nurse area larger- student growth- bigger clinic needed	SCE	HH	G
Creech Elementary	ELEM	Currently the gym and café have one speaker system. We can only use the microphone in one or the other not both. I am requesting a speaker system in the café for presentations and to be used during lunch time	SCE	HH	P
Creech Elementary	ELEM	Updated open concept serving line-update to KISD standards	Food Ser	HH	P
Creech Elementary	ELEM	Brighter back door lighting	Food Ser	HH	SS
Davidson Elementary	ELEM	Traffic study-enlarge the space available for bicycle parking to reduce students stepping off the sidewalk into traffic on the main drive into the school.Widen the main drive to allow double stacking of the car rider vehicles at dismissal	Emergency Management	1	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Davidson Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors	Emergency Management	2	SS
Davidson Elementary	ELEM	Install access control on the doors	Emergency Management	2017B	SS
East Transportation	OPER	Bus parking area and drives have areas that are sinking at the expansion joint	East Tran	2017B	BI
East Transportation	OPER	Controlled access to office area	East Tran	2	SS
East Transportation	OPER	More exterior cameras needed, upgrade existing	East Tran	2	SS
East Transportation	OPER	No cameras located in the driver lounge area- room 120	East Tran	2	SS
East Transportation	OPER	Additional outside exit in office area	East Tran	2	P
East Transportation	OPER	Areas in the parking lot that hold water, even after a light rain	East Tran	2	BI
East Transportation	OPER	Parking lot lighting insufficient for security at night	East Tran	2017B	SS
East Transportation	OPER	Install a traffic light on Greenhouse at Ashley. Since Greenhouse was extended south to I-10 increased traffic makes exiting difficult	2010	2017B	SS
East Transportation	OPER	Carpet replacement	M&O	2	RC
East Transportation	OPER	Above ground fuel stations at East and West Transportations- compliance with underground storage replacement because current under ground tanks have exceeded their useful service life	East Tran	2017B	BI
East Transportation	OPER	Security access for dispatch and administration wing-only one way in and one way out. No other exit in case of emergency	East Tran	2017B	SS
ESC	OPER	Finish out shell space	2010	GOF	G
ESC	OPER	Misc. reconfiguration of existing office	2010	GOF	G
ESC	OPER	Larger freezer/coolers store food/beverages for the following: ESC Catering/LMC Conference ESC Café/Rhodes Stadium *hard to keep food to proper temperature required by Health Dept.*	Food Ser	2	P
ESC	OPER	We have no warmers/coolers (Reach in) on our serving line (ESC-Café) -No warmers to hold foot at temp. use back warmers located in the LMC part of the kitchen for catering, which is provided during the day at the same time serving breakfast/lunch for ESC -These warmers are also used when LMC concessions are in use	Food Ser	2	P
ESC	OPER	Renovate serving line(only have 3 wells)- no room to keep food being served up to temperature required by Health Dept.		2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
ESC	OPER	Television for menu choices and pricing	Food Ser	2	P
ESC	OPER	Kitchen is divided between ESC and LMC(they are on 2 different thermostats and the back part of kitchen stays hot)	Food Ser	2017B	P
ESC	OPER	Parking lot has flooded and had to move our vans when we have down pours	Food Ser	GOF	BI
Exley Elementary	ELEM	Walk-in cooler/freezer replacement	Food Ser	3	RC
Exley Elementary	ELEM	Carpet replacement	M&O	2017B	RC
Exley Elementary	ELEM	Cafeteria often is dark and lights do not appear to be all the way on	JEE	3	BI
Exley Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse	Emergency Management	1	SS
Exley Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors	Emergency Management	2	SS
Exley Elementary	ELEM	Security- relocate the west wall/gate of the mechanical yard to eat of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day	Emergency Management	2	SS
Exley Elementary	ELEM	Additional ventilation improvement to the clinic (smells tend to linger and not dissipate)	M&O	GOF	BI
Exley Elementary	ELEM	Sink hole on the SW side of the staff parking lot (reported over 6 months ago)	JEE	GOF	BI
Exley Elementary	ELEM	Doubling the depth of the front sidewalk along parent drive to accommodate walkers, car riders and bike riders while keeping a safe distance from vehicles	JEE	2	SS
Fielder Elementary	ELEM	Walk in cooler/freezer replacement	Food Ser	2017B	RC
Fielder Elementary	ELEM	Carpet replacement	M&O	2017B	RC
Fielder Elementary	ELEM	Renovate art rooms and reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	2010	2017B	P
Fielder Elementary	ELEM	Additional parking needed	FE	3	G
Fielder Elementary	ELEM	Cabinets in the teachers' lounge needs to be updated	FE	2017B	RC
Fielder Elementary	ELEM	Cafeteria/Gym-built in cabinets are needed for storage	FE	2017B	P
Fielder Elementary	ELEM	Lack of storage throughout campus	FE	2017B	P
Fielder Elementary	ELEM	More adult restrooms are needed	FE	2017B	P
Fielder Elementary	ELEM	Textbook room is too small to accommodate our campus	FE	2017B	P
Fielder Elementary	ELEM	LGI space as with current prototypes	FE	2017B	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Fielder Elementary	ELEM	Fence to divide the greenbelt and front parking lot	FE	2017B	SS
Fielder Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors.	Emergency Management	2017B	SS
Fielder Elementary	ELEM	Additional grade level classrooms to accommodate the grade level and programs that have been permanently located in portables for over 10 years	FE	2017B	G
Fielder Elementary	ELEM	Grade level planning and collaboration rooms	FE	2017B	P
Fielder Elementary	ELEM	Teachers do not have storage space because there are no planning rooms. Adult restrooms are scarce and teachers are using the same restroom with students	FE	2017B	P
Fielder Elementary	ELEM	The school in general is never consistently cool. The gym has gotten better since repairs to condenser and duct work were done. However, many classrooms are hot on a daily basis. Teachers have quit reporting the issue because when we do, nothing seems to happen. The teacher lounge and ADA Office are hot all the time	FE	2017B	E
Fielder Elementary	ELEM	The student restrooms are dimly lit	FE	2017B	SS
Fielder Elementary	ELEM	When too many items are plugged in along the east wall of the gym, the breaker will trip, sometimes tripping the gym and library outlets	FE	2017B	BI
Fielder Elementary	ELEM	There is not an electrical outlet in the book room. One is needed.	FE	2017B	P
Fielder Elementary	ELEM	Cabinets are needed in the PE storage room	FE	2017B	P
Fielder Elementary	ELEM	Wall outlets and switches...there are a variety of controls and switches throughout the building. It would be nice if they were all matching and automatic timed out switches.	FE	2017B	E
Fielder Elementary	ELEM	All restroom are old with floor finishing that do not clean well	FE	2017B	RC
Fielder Elementary	ELEM	The role of the front office has changed over the years. Our configuration is outdated and there are not enough offices. The counselor is in what was a Conference room. The ADA is in a hallway. The Instructional Coordinator is not with the rest of the admin team.	FE	2017B	P
Fielder Elementary	ELEM	The teacher's lounge is very small and often very hot with poor air circulation	FE	2017B	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Fielder Elementary	ELEM	The oddly shaped music room could be reconfigured into possible two classrooms. We need a 2nd classroom for the 2nd music teacher. This is currently a portable.	FE	2017B	P
Fielder Elementary	ELEM	There needs to be a 2nd Art room for the 2nd Art teacher	FE	2017B	P
Fielder Elementary	ELEM	The janitorial storage and office areas are very small. There are always issues with the janitorial spaces during our yearly Fire Marshall visits.	FE	2017B	SS?
Fielder Elementary	ELEM	We need more parking. Several spaces could be easily added.	FE	2017B	G
Fielder Elementary	ELEM	Updated open concept serving line-update to KISD standards	Food Ser	2017B	P
Fielder Elementary	ELEM	New air curtain for back door low power, prevention of flying pests	Food Ser	2017B	E
Fielder Elementary	ELEM	Small prep table-replacement for unused stove top	Food Ser	2017B	P
Fielder Elementary	ELEM	Hood vent filters(4)-replacement for damaged ones	Food Ser	2017B	RC
Fielder Elementary	ELEM	New ovens- replacement for older units	Food Ser	2017B	RC
Fielder Elementary	ELEM	Brighter back door lighting for security reasons	Food Ser	2017B	SS
Food Service	OPER	Redesign of reception area to accommodate better security	Food Ser	2017B	SS
Food Service	OPER	Increased ventilation to include large fans and/or two rolling doors on northwest side of building	Food Ser	2	BI
Food Service	OPER	Warehouse needs wire racking for shelves	Food Ser		P
Franz Elementary	ELEM	Key card access for staff-front entry, staff parking lot door by fine arts(609-601)	FES	2017B	SS
Franz Elementary	ELEM	Library- add book shelves or recharging stations with outlets by the doors (replacing atlas, dictionary and magazine stands including more surge protected outlets at the end of the shelves)	FES	3	P
Franz Elementary	ELEM	Provide for playground shade structure	M&O	GOF	SS
Franz Elementary	ELEM	Carpet replacement	M&O	2017B	RC
Franz Elementary	ELEM	Need cabinets above counter in the music rooms for extra storage of instruments	FES	3	P
Franz Elementary	ELEM	Accordion door that divides the gym/cafeteria needs a lock	FES	GOF	P
Franz Elementary	ELEM	All water faucets should have motion sensors to conserve water	FES	GOF	E
Franz Elementary	ELEM	Traffic study-in anticipation of the future extension of Westgreen north over the flood control ditch build a ring road around the school site and connecting to the east drive for the Morton Ranch complex. Install fencing between the ring road and the playground to reduce unauthorized access	Emergency Management	2017B	G/SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Franz Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse	Emergency Management	1	SS
Franz Elementary	ELEM	Security- relocate the southeast wall/gate of the mechanical yard to northwest of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day	Emergency Management	2	SS
Franz Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors	Emergency Management	2	SS
Golbow Elementary	ELEM	Relocate dish machine to make more room for lines in the front. Redesign to fit more space for serving lines	Food Ser	2014B	P
Golbow Elementary	ELEM	New serving line with frost tops-increasing student enrollment. Able to serve more students in open concept serving lines, update to current KISD standards. Hard to keep food to temperature to meet health regulations	Food Ser	2014B	P
Golbow Elementary	ELEM	Expand cooler and freezer- increase in menu items served to customers	Food Ser	2014B	P
Golbow Elementary	ELEM	Freezer with an external door-existing freezer door is located inside the cooler which makes accessing and accepting deliveries for the freezer very difficult	Food Ser	2014B	P
Golbow Elementary	ELEM	If not addressed in comprehensive renovation, reconfigure drives and parking to create off street stacking for the car-rider line.	Emergency Management	2017B	G
Griffin Elementary	ELEM	Walk in cooler/freezer replacement	M&O	3	RC
Griffin Elementary	ELEM	Carpet replacement	M&O	1	RC
Griffin Elementary	ELEM	Add a more durable wall covering over the bottom third of all hallways	MGE	3	P
Griffin Elementary	ELEM	Add doors to both ends of the LGI. Glass doors would provide a sound barrier while allowing visual access to events held within the LGI	MGE	2	P
Griffin Elementary	ELEM	Traffic study-create a ring road or reconfigure driveways to create additional onsite car-rider vehicle stacking. This will reduce vehicles stopped on Fry Rd., improve safety for students who cross Fry at the uncontrolled school crosswalk to the Avalon neighborhood, and improve efficiency of dismissal	Emergency Management	2	G/SS
Griffin Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse	Emergency Management	1	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Griffin Elementary	ELEM	security- relocate the east wall/gate of the mechanical yard to west of the kitchen doors so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be locked during the day	Emergency Management	2	SS
Griffin Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors	Emergency Management	2	SS
Griffin Elementary	ELEM	Close in LGI-current design is not conducive to mtgs/classes/PDR due to noise level from hallways	MGE	3	P
Griffin Elementary	ELEM	Paint exterior of building	MGE	GOF	RC
Griffin Elementary	ELEM	Install microphone system	MGE	3	BI
Griffin Elementary	ELEM	Additional hotspots within the building	M&O	3	E
Griffin Elementary	ELEM	Extend the front walkway cover on a T for protection from the weather while loading and unloading vehicles	M&O	3	BI
Hayes Elementary	ELEM	Walk in cooler/freezer replacement	Food Ser	2	RC
Hayes Elementary	ELEM	Modify north drive to accommodate bus loading and parking lot to allow car rider stacking	Safety	2017B	G/P
Hayes Elementary	ELEM	Carpet replacement	M&O	1	RC
Hayes Elementary	ELEM	Cracks in walls throughout the building that need to be repaired	JHE	GOF	BI
Hayes Elementary	ELEM	Door frames need to be repainted	JHE	GOF	RC
Hayes Elementary	ELEM	Need cabinets/storage built at the end of each grade level hallway	JHE	2	P
Hayes Elementary	ELEM	Update stage area	JHE	2	P
Hayes Elementary	ELEM	Need LGI space(s)	JHE	2	P
Hayes Elementary	ELEM	Need storage cabinets in room 10(Pre-K classroom) as there is no storage in this room	JHE	2	P
Hayes Elementary	ELEM	Need storage/cabinets in Speech room	JHE	2	P
Hayes Elementary	ELEM	Art- adding cupboard doors to some of the open bookshelves in the room would be a great improvement to lessen the visual stimulus in the art room as well as make the room more tidy and spacious. We also do not have a handicap accessible sink and we do have students in wheelchairs as this campus who currently are taken to the bathroom when it is necessary for them to wash their hands	JHE	2	P
Hayes Elementary	ELEM	Door to enter Speech room opens into the hallway . Safety hazard due to students walking by throughout the day. A student could be hit by the door as it is opened if they pass by in front of the door. A door that opens to inside the room would be safer	JHE	2	

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Hayes Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors.	Emergency Management	2	SS
Hayes Elementary	ELEM	Reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	JHE	2	P
Hayes Elementary	ELEM	Renovate art rooms	JHE	2	P
Hayes Elementary	ELEM	Serving line updated frost tops added- Health Dept. regulations changing	Food Ser	2	P
Hayes Elementary	ELEM	A more open concept with windows seperating the kitchen and cafeteria would bring Hayes up to KISD standards, as well as updating the serving lines	Food Ser	2	P
Holland Elementary	ELEM	library needs additional outlets to support personal learning devices	BHE	3	P
Holland Elementary	ELEM	Additional cabinets needed in Kinder kitchen room K10	BHE	3	P
Holland Elementary	ELEM	Additional storage needed in literacy library room 801	BHE	3	P
Holland Elementary	ELEM	Closet built at the back of the motor lab room K9	BHE	3	P
Holland Elementary	ELEM	Instructional coach office	BHE	3	P
Holland Elementary	ELEM	Wall cabinets needed for Diag in room A14	BHE	3	P
Holland Elementary	ELEM	Fine arts/Art- shelf unit for storage	Fine Arts	3	P
Holland Elementary	ELEM	Carpet replacement	BHE		RC
		Lobby & teacher lounge furniture	BHE	2	RC
Holland Elementary	ELEM	Fine Arts/Art-shelving for drying clay-kiln closet	Fine Arts	3	P
Holland Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse	Emergency Management	1	SS
Holland Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors	Emergency Management	2	SS
Holland Elementary	ELEM	Security- relocate the northeast wall of the mechanical yard to southwest of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day	Emergency Management	2	SS
Holland Elementary	ELEM	Sound system upgrades	BHE	GOF	RC
Holland Elementary	ELEM	Classroom for growth in 3rd (currently using LGI)	BHE	3	G
Hutsell Elementary	ELEM	New playground equipment, add/develop space for soccer (goals) softabll(backstop)	2010	2017B	P
Hutsell Elementary	ELEM	Chiller replacement	M&O	2017B	RC
Hutsell Elementary	ELEM	Addition of sidewalks in the front of the school for parent pick-up	HE	GOF	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Hutsell Elementary	ELEM	Modify driveways separate from buses and private vehicles	Safety	1	P
Hutsell Elementary	ELEM	Swap the teachers' lounge and the teachers' workroom for better use of space	HE	1	P
Hutsell Elementary	ELEM	Provide for fire sprinkler system	2006	1	
Hutsell Elementary	ELEM	Traffic safety-enlarge driveway on west side of the school, cover drainage and build awning to create a new bus loading location. This will allow more effective car rider stacking and reduce the impact on Franz Rd. at dismissal	Emergency Management	1	G/SS
Hutsell Elementary	ELEM	Security- install or modify doors from the main north-south hall into the classroom areas with access control to isolate classrooms from intruders. Three sets of doors identified as needed for this.	Emergency Management	1	SS
Hutsell Elementary	ELEM	Main hallways and pod areas need painting- last year we received flooring and the paint was damaged when base boards were removed. The current wallpaper is no longer available.	HE	1	RC
Hutsell Elementary	ELEM	Lighting (additional) in the gym and cafeteria is dim and cast shadows. This may have already planned for renovation repair because it has been discussed previously	HE	GOF	E
Hutsell Elementary	ELEM	Drainage issues in parking lot adjacent to bus ramps. Significant ponding where cars are parked and making impossible to get in cars.	HE	GOF	BI
Katy Elementary	ELEM	Provide for playground shade structure	M&O	2014B	SS
Katy Elementary	ELEM	Renovation	FCP	1	RC
Katy Elementary	ELEM	Add shelving in Literacy Library	2010	GOF	P
Katy Elementary	ELEM	Install floor drains in existing staff restroom (in addition)	2010	1	BI
Katy Elementary	ELEM	more outlets in classrooms, cafeteria and labs	2010	1	BI
Katy Elementary	ELEM	New sound, lighting system for stage & gym	2010	1	RC
Katy Elementary	ELEM	Renovate 2nd and 5th grade restrooms	2010	1	RC
Katy Elementary	ELEM	Replace classroom casework in original building	2010	1	RC
Katy Elementary	ELEM	Replace operable wall at gym/cafeteria	2010	1	RC
Katy Elementary	ELEM	Fine Arts/Art- cabinets on north side of room are rough and children may get splinters from the rough wood. While they are replacing the surface, perhaps the cabinetry could be built to be more art friendly, as in the new art rooms	Fine Arts	1	RC
Katy Elementary	ELEM	Fine Arts/Art-ancient storage cabinets need to be replaced- doors don't close, sagging shelves	Fine Arts	1	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy Elementary	ELEM	Fine Arts/Music- closet shelving needs to be replaced to accommodate guitar storage, text book storage, and open shelving for other items. Current shelving too narrow.	Fine Arts	1	RC/P
Katy Elementary	ELEM	Fine Arts/Music-new curtain is needed. Stage floor is in terrible condition. Drop ceiling for better sound production is needed. Shelving needed in storage closet on stage	Fine Arts	1	RC
Katy Elementary	ELEM	Walk-in cooler/freezer replacement	Food Ser	1	RC
Katy Elementary	ELEM	Kitchen-replace 2 compartment sink with 3 compartment sink as per Health Dept. code and move closer to dish room area for more efficiency	Food Ser	1	RC
Katy Elementary	ELEM	Kitchen- replace ovens and steamers	Food Ser	1	RC
Katy Elementary	ELEM	Kitchen-repurpose unused space in mop sink area	Food Ser	1	RC
Katy Elementary	ELEM	Kitchen- add hand sink	Food Ser	1	RC/P
Katy Elementary	ELEM	Kitchen-combine 2 small storage areas for greater efficiency	Food Ser	1	RC/P
Katy Elementary	ELEM	Kitchen- expand dish room area and repair missing floor tiles	Food Ser	1	RC/P
Katy Elementary	ELEM	Kitchen- new serving line with frost tops for increased fruit and vegetables choices and built in ice cream freezer	Food Ser	1	RC/P
Katy Elementary	ELEM	Kitchen-relocate washer and dryer	Food Ser	1	RC
Katy Elementary	ELEM	Kitchen- remove butcher table and stove top which are not in use	Food Ser	1	RC/P
Katy Elementary	ELEM	Kitchen-remove wall to move to open concept with glass windows as in the new campuses	Food Ser	1	RC/P
Katy Elementary	ELEM	Add charging stations for mobile devices	KE	1	T
Katy Elementary	ELEM	Close off locker rooms with wall	KE	1	P
Katy Elementary	ELEM	Drainage on playground is improved but still backs up with heavy rains	KE	GOF	BI
Katy Elementary	ELEM	Foyer has insufficient lighting	KE	1	BI
Katy Elementary	ELEM	Install whiteboards in classrooms	KE	1	P
Katy Elementary	ELEM	Intercome is not audible in gym where P.E. classes are in session	KE	1	RC
Katy Elementary	ELEM	Move wall in library closet back 2 ft. to provide for additional storage space	KE	1	P
Katy Elementary	ELEM	Provide additional classroom space	KE	1	P
Katy Elementary	ELEM	Provide additional parking spaces	KE	1	G
Katy Elementary	ELEM	Provide additional storage space	KE	1	P
Katy Elementary	ELEM	Provide additional student/staff restrooms	KE	1	P
Katy Elementary	ELEM	Replace HVAC system	KE	1	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy Elementary	ELEM	Restrooms need automatic water and automatic hand dryers to elimate continued paper being thrown in urinls and toilets	KE	1	RC
Katy Elementary	ELEM	General Safety- the corridor at the north end of the lobby is closed at both ends and very dark; open up the hallway and improve lighting	Emergency Management	1	SS/BI
Katy Elementary	ELEM	General Safety- resurface parking lots to reduce trip hazard	Emergency Management	1	RC
Katy Elementary	ELEM	Security- redesign door swing and add access control on doors between the reception hall and classroom halls	Emergency Management	1	SS
Katy Elementary	ELEM	Remark the parking spaces in front of the school as handicap parking only	Emergency Management	1	P
Katy Elementary	ELEM	Install longer sinks in the restrooms in the north wing would allow for more students to use wash station at one time and limit loss of time. Installing a facet sensor would eliminate loss of water.	KE	1	G
Katy Elementary	ELEM	The outside doors of build in wood cabinet in main campus classrooms (121-125,119-115,114-110,101-109) are in need of repair to address splinters, cracks, frays, and overall appearance	KE	1	RC
Katy Elementary	ELEM	Due in increases in student enrollment, we no longer have a multi-purpose room/LGI and have not for the past 3 years due to lack of classroom space. This limits our campus greatly in regards to planning for speakers or special events.	KE	1	G
Katy Elementary	ELEM	Additional hand sinks-update to Health Dept. standards	Food Ser	1	P
Katy Elementary	ELEM	Expand dish room/ replace dish machine- dish machine needs continual repair and return area not adequate	Food Ser	1	P
Katy Elementary	ELEM	Update serving lines to open per KISD standards- Dishroom needs to be expanded. Unused space on line or mop sink can be used for dishroom extension. Change 3 compartment sink to dishroom. Combine 2 storage areas. Old and unused equipment taken out stove top, butcher table, additional hand sinks needed	Food Ser	1	P
Katy High School	HS	PAC - replace all carpeting.	KHS	2014B	RC
Katy High School	HS	Additional surveillance cameras.	KHS	2017B	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy High School	HS	Ag - there are immediate needs for general classroom space and Ag lab spaces for courses such as floral design. The shop area is outdated and undersized for existing instructional demands. Currently, six teachers share an office designed for two.	KHS	2017B	P
Katy High School	HS	9th grade walk-in cooler/freezer replacement.	M&O	2	RC
Katy High School	HS	Roof-areas A1, A2, A8, A9, A14, A15, B1-B13, C1-C3, C7-C9, C11-C14, E1-E116.	M&O	2	RC
Katy High School	HS	Additional practice field.	Athletics	3	G
Katy High School	HS	Athletic storage - field house. Entry to second level athletic storage area is restrictive and dangerous.	Athletics	2017B	G
Katy High School	HS	Expansion of field house weight room.	Athletics	2017B	G
Katy High School	HS	Canopy area outside field house.	Athletics	2017B	BI
Katy High School	HS	Gearboss system for athletic storage.	Athletics	2017B	P
Katy High School	HS	Awning for life skills students at B lot for loading busses in bad weather.	KHS	2	BI
Katy High School	HS	Upgrade walkie talkie antenna.	KHS	GOF	T
Katy High School	HS	Competition field replacement.	Athletics	2017B	RC
Katy High School	HS	Additional science classrooms will be needed prior to the opening of high school 10.	KHS	2	G
Katy High School	HS	Capacity for student needs such as restrooms and cafeterias will also need to increase prior to opening of high school 10.	KHS	2	G
Katy High School	HS	General classroom space for classes such as English, math, social studies, and electives will also be needed.	KHS	2	G
Katy High School	HS	Re-key main campus.	KHS	2	RC
Katy High School	HS	Exterior doors in A100 are old & in very poor condition. Entrance to gym 3 needs renovation - water damage, plaster ceiling, concrete roof unrepairable, door damage & malodorous.	KHS	GOF	RC/BI
Katy High School	HS	Replace outdated exterior exits: Annex & A095, foyer of gym 3, end of vocational hall on the north side, east side of V9, near V12 (door is rusted out), both sets of doors at the back of the competition gym, doors (2) from A-hall to the back of the competition gym; door near A106 to the back of the competition gym, exist doors of west cafeteria.	KHS	2017B	RC
Katy High School	HS	There needs to be a secure entrance from the main building to the natatorium and to the field house. Currently, exterior door must be left open to allow students access for transitions between class periods.	KHS	GOF	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy High School	HS	Science lab storage area and exhaust should be updated.	KHS	2	P
Katy High School	HS	Replace old cabinets in A hall classrooms. Falling apart and takes up too much room.	KHS	2	RC
Katy High School	HS	Ventilation system in the A hall is poor. Any smells outside circulate through the classes.	KHS	2	RC
Katy High School	HS	Settling cracks - expansion joint across from B132, at B & C hall intersection, by B144 and across from B150.	KHS	2	BI
Katy High School	HS	Repaint A hall classrooms and halls.	KHS	GOF	RC
Katy High School	HS	V Hall renovation	KHS	2	RC
Katy High School	HS	PAC stage refurbishment	KHS	2	RC
Katy High School	HS	Teachers would like multi-staff restrooms near main campus teacher lounge/workroom.	KHS	2	P
Katy High School	HS	Provide Sparger (bubbler system) for diving well - puts compressed air into water to allow divers to learn new dives.	KHS	3	P
Katy High School	HS	Raised scoring table in natatorium - build a platform for computer console in seating area near bulkhead.	KHS	2017B	P
Katy High School	HS	Band hall - room for permanent seasonal storage space.	KHS	2	P
Katy High School	HS	Band hall - a larger 2nd ensemble room.	KHS	2	P
Katy High School	HS	Band hall - locker room redesign.	KHS	2	P
Katy High School	HS	Band hall - larger percussion storage room.	KHS	2	P
Katy High School	HS	Band hall - larger color guards storage room.	KHS	2	P
Katy High School	HS	Band hall - more practice rooms.	KHS	2	P
Katy High School	HS	Band hall - instrument repair/storage area.	KHS	2	P
Katy High School	HS	Larger band hall.	KHS	2	P
Katy High School	HS	Orchestra room needs a new built-in sound system.	KHS	2	P
Katy High School	HS	Orchestra room to be equipped with a built-in projector and screen similar to what exists in the band hall.	KHS	2	P
Katy High School	HS	Wi-Fi accessibility in orchestra.	KHS	2	T
Katy High School	HS	Orchestra room needs all new instrument lockers.	KHS	2	RC
Katy High School	HS	Practice rooms in the orchestra room need to be larger.	KHS	2	P
Katy High School	HS	Replace carpets in the orchestra room.	KHS	2	RC
Katy High School	HS	Move theater storage trailer at PAC loading dock closer to the natatorium to restrict students from getting behind trailer.	KHS	CAMPUS	BI
Katy High School	HS	Additional new cafeteria tables for growth & to replace worn out tables.	KHS	GOF	G

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy High School	HS	All doors in the orchestra room need to have locks installed on them.	KHS	2	P
Katy High School	HS	Interior hallway gates - move gate from outside of V1 to near B150 so that V-hall can be restricted during events in the Black Box.	KHS	UNDER REVIEW	P
Katy High School	HS	Move gate from outside the main campus clinic to end of the hallway near the attendance offices; with a gate in this location, the campus could be blocked off during events in the Competition Gym.	KHS	UNDER REVIEW	P
Katy High School	HS	A key hole to be installed on the back door of the orchestra room.	KHS	2	SS
Katy High School	HS	Weightroom expansion - coaches FH office renovation- safety & security/ functionality	Athletics	2017B	P
Katy High School	HS	Replace baseball outfield fence	Athletics	2017B	RC
Katy High School	HS	Replace bleachers in gyms	Athletics	2	RC
Katy High School	HS	Irrigation system update- all grass practice fields, baseball and softball. Convert all irrigation systems from "2 Core" to "conventional wiring system".	Athletics	GOF	RC
Katy High School	HS	8 new natatorium starting blocks	Athletics	2017B	P
Katy High School	HS	Replacement scoreboards	Athletics	2017B	RC
Katy High School	HS	Replace sound system in gym/ competition facilities	Athletics	2017B	RC
Katy High School	HS	Tennis court resurface	Athletics	2014B	RC
Katy High School	HS	Lighting and plumbing renovation of A-hall	KHS	GOF	BI
Katy High School	HS	Foyer area outside gym 3 needs renovation	KHS	GOF	P
Katy High School	HS	New alarm system	KHS	2	RC
Katy High School	HS	Solid doors on each of the stairwells prevents supervision and allows for improper student activity to occur	KHS	GOF	SS
Katy High School	HS	Exterior- lighting outside gym 3 is non existent. It is used for athletics and is very dark	KHS	3	SS
Katy High School	HS	Outside parking lot lights- inadequate lighting	KHS	2	SS
Katy High School	HS	Install new gym exterior doors for competition gym (gym 1) and gym 2. These exterior doors have many issues and do not always close appropriately	KHS	2017B	RC
Katy High School	HS	All of our field house & main campus locker rooms need new lockers. Many do not lock and are not functional for securing students items. Coaches indicated its been 12 years since lockers were installed.	KHS	2	RC
Katy High School	HS	Boys basketball needs a new laundry facility with new washers and dryers	KHS	2	RC
Katy High School	HS	PAC chairs need to be fixed and/or replaced	KHS	2	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy High School	HS	PAC stage is not level and needs to be sanded and repainted	KHS	2	RC
Katy Junior High	JH	Replacement of bleachers in the gym.	Athletics	2	RC
Katy Junior High	JH	Gearboss system for athletic storage.	Athletics	2	P
Katy Junior High	JH	Replacement of scoreboards in the gyms.	Athletics	2	RC
Katy Junior High	JH	Replacement of sound system in gym.	2006	2	RC
Katy Junior High	JH	Additional restroom space needed.	2010	2	P
Katy Junior High	JH	6th / 7th restroom updating.	KJH	2	RC
Katy Junior High	JH	Natural lighting would greatly enhance learning environment.	KJH	2	P
Katy Junior High	JH	Walk-in cooler/freezer replacement. Consider Food Service comment: increase freezer and cooler sizes and improve lighting	Food Ser	2	RC
Katy Junior High	JH	Kitchen - add above desk cabinets for storage.	Food Ser	2	P
Katy Junior High	JH	Kitchen - enlarge dry storage.	Food Ser	2	P
Katy Junior High	JH	Kitchen - increase food preparation area.	Food Ser	2	P
Katy Junior High	JH	Kitchen - relocate and replace dish machine with smaller unit to increase kitchen efficiency.	Food Ser	2	P
Katy Junior High	JH	Kitchen - remove one oven and hood vent from back of kitchen which are not used and repurpose area.	Food Ser	2	P
Katy Junior High	JH	Kitchen - replace ovens and steamers.	Food Ser	2	P
Katy Junior High	JH	Kitchen - update technology with TV monitors.	Food Ser	2	P
Katy Junior High	JH	Kitchen - remove snack bar windows and redesign into serving lines as at new junior highs.	Food Ser	2	P
Katy Junior High	JH	Kitchen - electronic menu for the snack bar.	Food Ser	2	P
Katy Junior High	JH	Kitchen - need a larger snack bar area.	Food Ser	2	P
Katy Junior High	JH	Kitchen - new dryer is needed in Food Service area.	Food Ser	2	P
Katy Junior High	JH	Kitchen - new warmers are needed in the snack bar.	Food Ser	2	P
Katy Junior High	JH	Kitchen - warmer door gaskets need replacing.	Food Ser	2	P
Katy Junior High	JH	Kitchen ceilings upgrade.	Food Ser	2	P
Katy Junior High	JH	Additional storage in manager office-increase in paperwork required to store for documentation of national school breakfast/lunch program	Food Ser	2	P
Katy Junior High	JH	7th grade addition to building.	KJH	2	G
Katy Junior High	JH	7th grade has no science lab areas.	KJH	2	P
Katy Junior High	JH	7th grade needs a new water fountain.	KJH	2	P
Katy Junior High	JH	Additional office areas in latest building addition.	KJH	2	P
Katy Junior High	JH	Refinish the floor on the stage.	KJH	GOF	RC
Katy Junior High	JH	Teachers' lounge could use new tables.	KJH	2	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Katy Junior High	JH	Update cafeteria w/ technology/tables.	KJH	2	RC
Katy Junior High	JH	Install light to illuminate intersection at Katy-Hockley Cutoff and north drive into support services.	KJH	2	SS
Katy Junior High	JH	Fence around all practice fields. Safety issues from ball going into the street, vandalism because of easy field access	Athletics	2017B	SS
Katy Junior High	JH	Shade Structures- covered area with electrical at entrance to FB field	Athletics	2	BI
Kilpatrick Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Kilpatrick Elementary	ELEM	science lab- do not have space for teachers to do science experiments	OKE	3	P
Kilpatrick Elementary	ELEM	we would like to have our LGI/OLA enclosed. We tried to dot his a few years ago but due to Fire Marshal rules it was going to take up about 3ft of space on each side to accommodate the door enclosure. We would like to see if there is another solution to this	OKE	3	P
Kilpatrick Elementary	ELEM	Walk-in cooler/freezer replacement.	M&O	3	RC
Kilpatrick Elementary	ELEM	The library needs additional shelves to house more books. We are out of space.	OKE	3	P
Kilpatrick Elementary	ELEM	Space for Literacy Library.	OKE	3	P
Kilpatrick Elementary	ELEM	Space for motor lab.	OKE	3	P
Kilpatrick Elementary	ELEM	Playground and soccer field do not have sufficient grass, and flood when it rains.	OKE	GOF	BI
Kilpatrick Elementary	ELEM	Roof replacement.	M&O	2017B	RC
Kilpatrick Elementary	ELEM	Need a place to store the choir risers. The curtains on the stage are tearing and need to be replaced.	OKE	GOF-Stage Curtins	P
Kilpatrick Elementary	ELEM	Traffic Safety- create a ring road around the perimeter of the school site or other mitigation to greatly increase car-rider stacking off of the public streets and improve safety of student loading operations.	Emergency Management	UNDER REVIEW	G/SS
Kilpatrick Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
Kilpatrick Elementary	ELEM	Security- relocate the east wall/gate of the mechanical yard to west of the kitchen doors so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
King Elementary	ELEM	We must leave the exterior door unlocked for staff entry in the morning - safety issue - need badge access for doors - especially with projected growth.	RKE	2017B	SS
King Elementary	ELEM	Lighting and security cameras - playground/portables - we have lost keys by staff/students - due to entering the building from the portables.	RKE	2	SS
King Elementary	ELEM	Walk-in cooler/freezer replacement	M&O	2	RC
King Elementary	ELEM	Gen/FA/intercom replacement	M&O	2017B	RC
King Elementary	ELEM	Chiller replacement	M&O	2017B	RC
King Elementary	ELEM	Roof replacement	M&O	2	RC
King Elementary	ELEM	Remove all vinyl on outside walls - add back tack boards in these areas.	2010	3	BI
King Elementary	ELEM	Gym - lights are dim - need to check all bulbs. Playground/portables - inadequate lighting. Dim lighting - kindergarten adult restroom. Also porches and sidewalks.	RKE	2	BI/E
King Elementary	ELEM	Traffic Safety- create a ring road around the perimeter of the school site or other mitigation to greatly increase car-rider stacking off of the public streets and improve safety of student loading operations.	Emergency Management	UNDER REVIEW	SS/G
King Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
King Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
King Elementary	ELEM	Security- relocate the south wall/gate of the mechanical yard to north of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
King Elementary	ELEM	Drainage between playgrounds and sidewalks lighting along back of building and temporary buildings	RKE	2	BI
King Elementary	ELEM	carpet and flooring	RKE	1	RC
Law Enforcement Center	OPER	Expand covered fleet parking.	LEC	3	G
Law Enforcement Center	OPER	Expand general assembly room.	LEC	3	G
Law Enforcement Center	OPER	Expand locker room.	LEC	3	G
Law Enforcement Center	OPER	Expand MDF room.	LEC	3	G
Law Enforcement Center	OPER	Expand secure employee parking.	LEC	3	G
Law Enforcement Center	OPER	Expand visitor parking.	LEC	3	G
Law Enforcement Center	OPER	Increase number of employee workstations.	LEC	3	G

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Law Enforcement Center	OPER	Secure storage for large size equipment (portable lighting, electronic signs, and off-road vehicles.	LEC	3	P
Law Enforcement Center	OPER	5 x 5 canopy over sallyport door	LEC	3	BI
Law Enforcement Center	OPER	Change out lockers to 3 tier	LEC	3	P
Law Enforcement Center	OPER	Relocate kennel	LEC	3	P
Law Enforcement Center	OPER	Replace gate on east entrance	LEC	2017B	P
Mayde Creek Elementary	ELEM	Enclose the library with glass windows and doors to allow for noise reduction from hallway traffic and to enhance safety.	MCE	3	P
Mayde Creek Elementary	ELEM	Hallway by back mailboxes is too dark.	MCE	3	SS
Mayde Creek Elementary	ELEM	More security cameras are needed in common areas and main hallways.	MCE	3	SS
Mayde Creek Elementary	ELEM	Playground needs more appropriate equipment for younger students.	MCE	2017B	P
Mayde Creek Elementary	ELEM	Pre-K playground and wall around it needs to be updated.	MCE	2017B	P
Mayde Creek Elementary	ELEM	Playground shade structure.	M&O	2014B	SS
Mayde Creek Elementary	ELEM	Foundation repair needed.	MCE	2017B	BI
Mayde Creek Elementary	ELEM	Create circulation driveway.	Safety	2017B	BI
Mayde Creek Elementary	ELEM	Bins/bookshelves needed for leveled readers, and math guided activities in all classrooms.	MCE	3	P
Mayde Creek Elementary	ELEM	Consistent doors and locks throughout the school.	MCE	3	RC
Mayde Creek Elementary	ELEM	Doors - update colors and consistency for aesthetics in line with newer and remodeled campuses.	MCE	3	RC
Mayde Creek Elementary	ELEM	Matching doors/cabinets in common areas/MPAs.	MCE	3	RC
Mayde Creek Elementary	ELEM	More parking.	MCE	2017B	G
Mayde Creek Elementary	ELEM	Need addition to both girls and boys restrooms for Pre-K.	MCE	3	BI/G
Mayde Creek Elementary	ELEM	One storage area for items like chairs, tables, desks, filing cabinets, or large items that will be used in the school throughout the year.	MCE	3	P
Mayde Creek Elementary	ELEM	Storage cabinets added in room 38 for 4/5th grade materials and math lab materials.	MCE	3	P
Mayde Creek Elementary	ELEM	Workroom needs another work space.	MCE	3	P
Mayde Creek Elementary	ELEM	Basketball backdrops are in need of paint or replacement in the gym.	MCE	GOF	RC
Mayde Creek Elementary	ELEM	Carpet replacement	M&O	1	RC
Mayde Creek Elementary	ELEM	Need affixed bulletin boards in 4th/5th grade wing.	MCE	3	P
Mayde Creek Elementary	ELEM	Need cork walls in classrooms in old sections of building. Cannot attach projects to cinder block walls.	MCE	3	P
Mayde Creek Elementary	ELEM	Doors to office should be locked at all times and people should be able to buzz them in using an electronic lock.	MCE	2017B	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Mayde Creek Elementary	ELEM	Front counter is too open. Someone could jump over it and access the rest of the school.	MCE	2017B	SS
Mayde Creek Elementary	ELEM	Safety lights installed on property next to the side of the road by crosswalk.	MCE	2017B	SS
Mayde Creek Elementary	ELEM	Window coverings/blinds for all classrooms on interior windows for lockdown safety.	MCE	3	SS
Mayde Creek Elementary	ELEM	Emergency lights needed in all classrooms. Only 4/5th grade wing has them.	MCE	3	SS
Mayde Creek Elementary	ELEM	Need a sidewalk going from the back door off the main hallway to the playground.	MCE	GOF	BI
Mayde Creek Elementary	ELEM	Water sits in the parking lot area for a long time, right under the big tree by the back door parking lot entrance.	MCE	GOF	BI
Mayde Creek Elementary	ELEM	Flood Mitigation- Recommend undertaking an engineering study to determine if a cost effective mitigation strategy exists. The study should consider a subgrade retaining wall on the greater sloped south and east sides, which are subject to stream scour, to stabilize the foundation and reduce the risk of future flood damage. The study should also consider mitigation of the flooding between the elementary and junior high schools, this could be in conjunction with traffic flow and parking lot improvements. Engineers should look for evidence that the columns have shifted from true vertical and that the overhead structural connections are in good condition. Flood mitigation- it is also possible that vehicles traveling along Greenhouse Road could create a wake that would push water into the school. The engineering study should look at ways to prevent rising water from entering the building, including water from wakes.	M&O	GOF	BI
Mayde Creek Elementary	ELEM	Security- install doors to isolate classroom spaces-in particular the classrooms for special education and for kindergarten.	Emergency Management	3	SS
Mayde Creek Elementary	ELEM	Security- reconfigure back parking to improve security of the portable buildings and reduce the possibility of a vehicle being used as a weapon at the back entrance to the school.	Emergency Management	2017B	SS
Mayde Creek Elementary	ELEM	Storage for student desks, chair, tables	MCE	3	P
Mayde Creek Elementary	ELEM	two rooms for testing (district specialties)	MCE	3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Mayde Creek Elementary	ELEM	excessive noise in cafeteria-hearing damage- need something to absorb sound	MCE	GOF	P
Mayde Creek Elementary	ELEM	Mailbox area not well lit in front office	MCE	3	BI
Mayde Creek Elementary	ELEM	light fixtures falling out of ceiling	MCE	GOF	BI
Mayde Creek Elementary	ELEM	Pre K hallway needs more lighting	MCE	2	BI
Mayde Creek Elementary	ELEM	More outlets to accommodate more technology	MCE	3	BI
Mayde Creek Elementary	ELEM	Old section of building-many of the cabinets need replacing from wear and tear	MCE	3	RC
Mayde Creek Elementary	ELEM	Work Room- need more counter and storage space	MCE	3	P
Mayde Creek Elementary	ELEM	corridors and entries- corners banged up	MCE	3	RC
Mayde Creek Elementary	ELEM	teacher lounge not centrally located	MCE	3	P
Mayde Creek Elementary	ELEM	Teachers restrooms are cramped	MCE	3	
Mayde Creek Elementary	ELEM	student restrooms in old part of building- partitions and doors are worn out	MCE	3	RC
Mayde Creek Elementary	ELEM	Kitchen- need new ovens, 4 ovens not operating correctly- safety issue	Food Ser	3	RC
Mayde Creek Elementary	ELEM	Kitchen- need new steamers	Food Ser	3	RC
Mayde Creek Elementary	ELEM	Kitchen- not enough room on food line for everything students need- no room for plates	Food Ser	3	P
Mayde Creek Elementary	ELEM	Choir room needs storage upgrade	MCE	3	P
Mayde Creek Elementary	ELEM	Art room needs storage upgrade	MCE	3	P
Mayde Creek Elementary	ELEM	Library needs sound proofing from hall traffic	MCE	3	P
Mayde Creek Elementary	ELEM	Literacy library needs more space	MCE	3	P
Mayde Creek Elementary	ELEM	science lab needs storage	MCE	3	P
Mayde Creek Elementary	ELEM	Janitorial rooms need upgrades- dirty, cramped, no storage shelves	MCE	GOF	P
Mayde Creek High School	HS	PAC needs new carpet (inside and foyer area.)	MCHS	2017B	RC
Mayde Creek High School	HS	Baseball facility renovation	Athletics	2017B	P
Mayde Creek High School	HS	Move aux. gym score plugs to west	Athletics	2014B	P
Mayde Creek High School	HS	Outdoor athletic areas need more light	Athletics	2017B	P
Mayde Creek High School	HS	Replace A/C & heat in comp. F P-Box.	Athletics	2	RC
Mayde Creek High School	HS	Replace aux. gym bleachers	Athletics	2017B	RC
Mayde Creek High School	HS	Replace comp. gym bleachers	Athletics	2017B	RC
Mayde Creek High School	HS	Replace tennis lights	Athletics	2017B	RC
Mayde Creek High School	HS	Wrestling facility	Athletics	2	P
Mayde Creek High School	HS	Theatre needs to have a classroom and a workshop attached to the black box or near the PAC similar to other schools.	MCHS	2	P
Mayde Creek High School	HS	Fine Arts Building renovation	MCHS	2	RC
Mayde Creek High School	HS	In serious need of speed bumps in parking lots.	MCHS	2	BI

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Mayde Creek High School	HS	Natorium - redesign lighting - currently the lights are over the pool. When one burns out, maintenance is unable to replace them. Move lights to the edges of the pool.	MCHS	2017B	SS
Mayde Creek High School	HS	Parking lots need re-striping.	MCHS	2017B	RC
Mayde Creek High School	HS	Clinic - large refrigerator with an ice maker and a waterline both clinics.	MCHS	2014B	P
Mayde Creek High School	HS	Repair, overlay and expand asphalt roads to create an effective and safe loop around the school and the MCHS fields on the west side of the bayou.	Safety	2017B	BI
Mayde Creek High School	HS	Replace aux gym scoreboard.	Athletics	2	RC
Mayde Creek High School	HS	Replace comp. field scoreboard.	Athletics	2	RC
Mayde Creek High School	HS	9th Grade walk-in cooler freezer.	Food Ser	2	RC
Mayde Creek High School	HS	Roof replacement - A1-A15, C9-C15, D1-D11	M&O	2	RC
Mayde Creek High School	HS	24x24 practice field storage- losing POD storage unit	Athletics	2017B	P
Mayde Creek High School	HS	4x24 Comp. Field storage- losing POD storage unit	Athletics	2017B	P
Mayde Creek High School	HS	10x10 tennis storage- losing POD storage unit	Athletics	2017B	P
Mayde Creek High School	HS	Install 5-10 security cameras- Comp. Field- vandalism occurs frequently	Athletics	2017B	SS
Mayde Creek High School	HS	Motion sensing lights for entire athletic- vandalism occurs frequently	Athletics	2017B	SS
Mayde Creek High School	HS	Replace comp field PA system- frequently malfunctions	Athletics	GOF	RC
Mayde Creek High School	HS	Irrigation system update- all grass practice fields, baseball and softball. Convert all irrigation systems from "2 core" to "conventional wiring system".	Athletics	GOF	RC
Mayde Creek High School	HS	Replace sound system in gym/ competition facilities	Athletics	2017B	RC
Mayde Creek High School	HS	Tennis court resurface	Athletics	2017B	RC
Mayde Creek High School	HS	Replace turf fields and add E-layer at all competition fields	Athletics	2017B	RC
Mayde Creek Junior High	JH	Repair, overlay and expand asphalt roads to create an effective and safe loop around the school and the MCHS fields on the west side of the bayou.	Safety	2017B	SS
Mayde Creek Junior High	JH	Walk-in cooler/freezer replacement.	Food Ser	2	RC
Mayde Creek Junior High	JH	Gearboss system for athletic storage.	Athletics	3	P
Mayde Creek Junior High	JH	Scoreboards replacement.	Athletics	2	RC
Mayde Creek Junior High	JH	Replace bleachers in gyms	Athletics	2	RC
Mayde Creek Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	2	
Mayde Creek Junior High	JH	Smashed in lockers near cafeteria- maintenance is not able to fix as of now	MCJH	2	RC
McDonald Junior High	JH	Building renovation incl kitchen	FCP	1	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
McDonald Junior High	JH	Intercom and clock system need to be updated including Kitchen.	MDJH	2014B	RC
McDonald Junior High	JH	New bleachers in the gym.	Athletics	1	RC
McDonald Junior High	JH	Camera system needs to be updated.	MDJH	1	SS
McDonald Junior High	JH	New science classrooms/labs	MDJH	1	P
McDonald Junior High	JH	Replace walk-in cooler/freezer incl shelving	M&O	1	RC
McDonald Junior High	JH	Gearboss system for athletic storage.	Athletics	1	P
McDonald Junior High	JH	Scoreboards for both gyms.	Athletics	1	RC
McDonald Junior High	JH	Replace lighting for the staff & gym parking lots.	Safety	2017B	RC
McDonald Junior High	JH	Emergency lighting needs to be updated.	MDJH	1	RC
McDonald Junior High	JH	Expand and reconfigure locker rooms in gyms.	MDJH	1	P
McDonald Junior High	JH	Need a covered area at car pick-up area.	MDJH	1	P
McDonald Junior High	JH	Kitchen - additional steamer needed.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - back-up lights slow to turn on.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - ceiling tiles replaced or painted.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - consolidate pantries to make one large one for more efficiency.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - inadequate lighting throughout kitchen.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - larger freezer to accommodate items sold.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - new milk coolers.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - paint.	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - expand pantry area	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - renovate restroom area	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - additional hand sinks	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - new dish machine	Food Ser	1	RC
McDonald Junior High	JH	Kitchen - snack bar area update.	Food Ser	1	RC
McDonald Junior High	JH	Fine Arts/Art - need a sturdy, appropriate sized space for the paper cutter.	Fine Arts	1	P
McDonald Junior High	JH	Fine Arts/Art - new stools with backs, that do not rock on legs with missing feet.	Fine Arts	1	RC
McDonald Junior High	JH	Fine Arts/Art - replace the desks with tables for more working room.	Fine Arts	1	RC
McDonald Junior High	JH	Need new cafeteria tables.	MDJH	GOF	RC
McDonald Junior High	JH	Fine Arts/Art - electric plugs should be moved away from the sinks.	Fine Arts	1	BI
McDonald Junior High	JH	Replace bleachers in gyms	Athletics	1	RC
McDonald Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	1	
McDonald Junior High	JH	Tennis court resurface	Athletics	2017B	RC
McMeans Junior High	JH	Security cameras/additions.	MMJH	2017B	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
McMeans Junior High	JH	Weight room addition and new athletic locker/locks for locker rooms.	Athletics	2	RC
McMeans Junior High	JH	Library has only two outlets in the back portion, which are inadequate for use for meetings or staff development when several items need to be plugged in.	MMJH	2014B	P
McMeans Junior High	JH	Library renovation-shelves/outlets.	MMJH	2014B	P
McMeans Junior High	JH	Walk-in cooler/freezer replacement.	M&O	2	RC
McMeans Junior High	JH	HVAC update/chillers.	M&O	2017B	RC
McMeans Junior High	JH	Gearboss system for athletic storage.	Athletics	2	P
McMeans Junior High	JH	Scoreboards (both gyms) replacement.	Athletics	2017B	RC
McMeans Junior High	JH	Additional storage.	MMJH	2	P
McMeans Junior High	JH	Intercom and clock systems replacement.	MMJH	2017B	RC
McMeans Junior High	JH	New paint throughout building.	MMJH	GOF	RC
McMeans Junior High	JH	New sound system in cafeteria.	MMJH	2	RC
McMeans Junior High	JH	Plumbing updated.	MMJH	2	RC
McMeans Junior High	JH	Additional science lab rooms.	MMJH	2	P
McMeans Junior High	JH	Seated risers for choir room.	MMJH	CAMPUS	P
McMeans Junior High	JH	Clinic doesn't have a stretcher, or its own AED unit. There is one wheelchair located there. Another in the gym areas would be helpful.	MMJH	FFE	P
McMeans Junior High	JH	Need several gates which would provide access to the equestrian center in the event of an emergency.	MMJH	2	SS
McMeans Junior High	JH	Repaint all gyms and athletic areas. Paint old and distressed	Athletics	GOF	RC
McMeans Junior High	JH	Replace bleachers in gyms	Athletics	2	RC
McMeans Junior High	JH	Replace athletic lockers	Athletics	2	RC
McMeans Junior High	JH	Replacement scoreboards	Athletics	2017B	RC
McMeans Junior High	JH	Replace sound system in gym/competition facilities	Athletics	2017B	RC
McMeans Junior High	JH	Shade Structures- covered area with electrical at entrance to FB FIELD	Athletics	2	
McMeans Junior High	JH	Tennis court resurface	Athletics	2	RC
McMeans Junior High	JH	Storage inside to store indoor PE and Athletic Gear	Weightroom Expansion	2	P
McMeans Junior High	JH	New lockers for boys and girls gym- broken, disrepair, no embeded locks	MMJH	2	RC
McMeans Junior High	JH	New lighting in cafetria hallway- lighting is old and very dim	MMJH	2017B	BI/E
McMeans Junior High	JH	Resurface track and add lane to increase functionality and safety	MMJH	2	RC
McMeans Junior High	JH	Sensor lighting for classrooms to save energy	MMJH	2017B	E
McMeans Junior High	JH	Outside water fountain- Student access during PE and Athletics	MMJH	2	
McMeans Junior High	JH	Repainting of bathrooms- worn from age and use	MMJH	GOF	RC
McMeans Junior High	JH	New water fixtures in all bathrooms- antiquated equipment	MMJH	2	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
McMeans Junior High	JH	New motor for basketball goals-increase functionality	MMJH	GOF	RC
McMeans Junior High	JH	Wind screens for tennis courts-increase functionality	MMJH	GOF	P
McMeans Junior High	JH	Several areas where cement is chipped or broken including the exposure of rebar.	MMJH	GOF	BI
McMeans Junior High	JH	Inadequate drainage in area outside of gym causing muddy and slippery area. Labeled K on map	MMJH	GOF	BI
McMeans Junior High	JH	No outside lighting in back of school. Several lights in teacher parking lot burnt out. Inadequate lighting in that area in general.	MMJH	2	SS
McMeans Junior High	JH	Sound absorbing panels installed in room 184. Classroom has very strong echo sound from high walls	MMJH	2	P
McMeans Junior High	JH	Sink and water access for classrooms 131,133,141,143,145. These are science classrooms	MMJH	2	P
McMeans Junior High	JH	Remove snack bar area and change to serving lines to increase speed of service upgrade to KISD standards increase displays of food meet menu and health dept requirements	Food Ser	2	P
McMeans Junior High	JH	upgrade serving lines - add cold/frost tops - add water spouts to fill serving lines Upgrade to KISD standards, meet menu and Health Dept. requirements	Food Ser	2	P
McMeans Junior High	JH	Replace walk in cooler/freezer. Slipping issue in freezer- ice formation under the blowers Cooler- mold issue when closed up for any length of time (summer, winter break)	Food Ser	2	P/RC
McMeans Junior High	JH	Additional data outlets to support programs	MMJH	2	P
McMeans Junior High	JH	Classrooms for Newcomer program	MMJH	2	P
McRoberts Elementary	ELEM	Exiting doors throughout building to have built-in scanners.	PME	2017B	
McRoberts Elementary	ELEM	Generator/FA/intercom replacement to address campus comment regarding muffled sound on intercom.	PME M&O	2017B	RC
McRoberts Elementary	ELEM	Walk-in cooler/freezer replacement.	M&O	2	RC
McRoberts Elementary	ELEM	Hallway analogy clocks are never correct. All should be replaced.	PME	2	RC
McRoberts Elementary	ELEM	Convert existing locker rooms into useable space possibly storage.	2010	2	P
McRoberts Elementary	ELEM	Renovate art rooms.	2010	2	P
McRoberts Elementary	ELEM	Reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	2010	2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
McRoberts Elementary	ELEM	Fine Arts/Music - both rooms need more outlets on all 4 sides accessible in the areas we teach in.	Fine Arts	2	P
McRoberts Elementary	ELEM	Fine Arts/Music - we have 2 metal closets - they are in good condition but would like to add a couple more.	Fine Arts	2	P
McRoberts Elementary	ELEM	Traffic Safety- create a ring road around the perimeter of the school site or other mitigation to greatly increase car-rider stacking off of the public streets and improve safety of student loading operations.	Emergency Management	2017B	SS/G
McRoberts Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors.	Emergency Management	2	SS
McRoberts Elementary	ELEM	Cabinets needed in rooms in need of open doorway in divider wall paneling	PME	2	
McRoberts Elementary	ELEM	Built in speaker system in gymnasium	PME	2	
McRoberts Elementary	ELEM	fire alert system in classes are not loud	PME	2017B	SS
McRoberts Elementary	ELEM	Restrooms on B/C need a teacher stall (stall with wall that touches floor)	PME	2	
McRoberts Elementary	ELEM	Water fountain on hall B/C leaks on left side	PME	WO	BI
McRoberts Elementary	ELEM	Replacement of reach in coolers	Food Ser	2	RC
McRoberts Elementary	ELEM	Frost tops for serving lines	Food Ser	2	RC
McRoberts Elementary	ELEM	Replace dish machine	Food Ser	1	RC
McRoberts Elementary	ELEM	Ceiling tile replacement	Food Ser	GOF	RC
McRoberts Elementary	ELEM	Open up serving line to storefront- upgrade to KISD standards increase participation- meet customer needs	Food Ser	2	RC
McRoberts Elementary	ELEM	Campus marque needs to be replaced	PME	GOF	RC
Memorial Parkway Elementary	ELEM	Outdoor basketball area, other KISD JH's have one	Athletics	2014B	P
Memorial Parkway Junior High	JH	Resurface track	Athletics	1	RC
Memorial Parkway Junior High	JH	Replace both softball backstops, horrible condition and a safety issue	Athletics	2	RC
Memorial Parkway Junior High	JH	Replace bleachers in gyms	Athletics	2014B	RC
Memorial Parkway Junior High	JH	Replacement scoreboards	Athletics	3	RC
Memorial Parkway Junior High	JH	Replace sound system in gym/ competition facilities	Athletics	2014B	RC
Memorial Parkway Junior High	JH	Shade Structures- covered area with electrical at entrance to FB field	Athletics	3	
Memorial Parkway Junior High	JH	Tennis court resurface	Athletics	2017B	RC
Memorial Parkway Junior High	JH	Weight room equipment needs updating. Some conversation has occurred with athletics department	MPJH	3	P
Memorial Parkway Junior High	JH	Built in instrument storage in band and orchestra needs updating	MPJH	3	RC
Merrell Center	OPER	Replace carpet	Merrell Ctr	HH	RC
Merrell Center	OPER	Replace wood flooring	Merrell Ctr	HH	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Merrell Center	OPER	Replace wire rope guardrail solution throughout the facility.	Merrell Ctr	2	RC
Merrell Center	OPER	Replacement/repair of retractable risers seating.	Merrell Ctr	HH	RC
Merrell Center	OPER	Installation of replacement seat arms throughout the upper arena bowl. Original seat arms material failing constantly. Replacement arms are steel with a longer life span. We have already started replacing as needed. Within 5 years, we need to replace them all. Approximately 4,000 seats.	Merrell Ctr	GOF	RC
Merrell Center	OPER	Vehicles can drive into lobby. Install vehicle barriers/bollards.		2	SS
Merrell Center	OPER	Add oven	Food Ser	3	P
Merrell Center	OPER	Add microwave	Food Ser	3	P
Merrell Center	OPER	Connectless steamer	Food Ser	3	P
Merrell Center	OPER	We will likely need to purchase a replacement portable sports floor in the next 2-3 years. The existing floor has been in use since 2005 and is starting to show normal wear and tear, but could begin failing in the upcoming future.	Merrell Ctr	HH	RC
Miller Career & Technology Center	HS	Library doors - must be hooked open or closed and locked. Safety issue if an intruder walks in through the front door.	MCTC	2	SS
Miller Career & Technology Center	HS	Location of student bus drop-off and pick-up area is in a lane that car drivers must cross to access the school or their vehicles at departure time.	MCTC	2	SS
Miller Career & Technology Center	HS	Replace cooler/freezer	M&O	2	RC
Miller Career & Technology Center	HS	Carpet replacement.	M&O	2	RC
Miller Career & Technology Center	HS	Expand Culinary Arts	MCTC	2	
Miller Career & Technology Center	HS	Implement Building Trades Program	MCTC	2	
Miller Career & Technology Center	HS	Expand Digital Audio classroom	MCTC	2	
Miller Career & Technology Center	HS	Locker reconfiguration	MCTC	2	
Morton Ranch Elementary	ELEM	I.D. swipe/keyless entry	MRE	2017B	SS
Morton Ranch Elementary	ELEM	Playground shade structure.	M&O	2014B	SS
Morton Ranch Elementary	ELEM	Gym/Cafeteria flooring replacement.	M&O	2017B	RC
Morton Ranch Elementary	ELEM	Create circulation driveway on west connecting Morton Ranch west drive to Morton Ranch north drive.	Safety	2017B	P
Morton Ranch Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Morton Ranch Elementary	ELEM	Security- relocate the south wall of the mechanical yard to north of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Morton Ranch Elementary	ELEM	Security-create doors to isolate special education and kindergarten classroom areas from the rest of the building for security- install access control on the doors.	Emergency Management	2	SS
Morton Ranch High School	HS	30x30 storage building for track pits.	Athletics	GOF	P
Morton Ranch High School	HS	Brick dugouts @ softball and baseball fields.	Athletics	2017B	P
Morton Ranch High School	HS	Additional security cameras added outside and older ones replaced.	MRHS	2017B	LS
Morton Ranch High School	HS	Wooden fence for baseball.	Athletics	2017B	P
Morton Ranch High School	HS	PAC - scene shop - garage doors need a lift. Very heavy to open and close. The crank is very dangerous. Sound shells need repaired, replaced or removed. Stage floor is splintering.	MRHS	GOF	LS
Morton Ranch High School	HS	Amps in library AV storage is not adequate to charge all new technology products.	MRHS	GOF	P
Morton Ranch High School	HS	9th grade walk-in cooler/freezer replacement.	M&O	2	RC
Morton Ranch High School	HS	Main walk-in cooler/freezer replacement.	M&O	2	RC
Morton Ranch High School	HS	Carpet replacement.	M&O	2017B	RC
Morton Ranch High School	HS	Walk in Floral Cooler	CTE	2017B	P
Morton Ranch High School	HS	Replace all athletic lockers.	Athletics	2	RC
Morton Ranch High School	HS	Create a circulation drive along the south edge of the property to connect Raintree Village Dr. to the east drive into MRHS and MRJH	Safety	2017B	P
Morton Ranch High School	HS	Replace turf at competition field.	Athletics	2017B	RC
Morton Ranch High School	HS	Fans needed in all locker rooms.	MRHS	2	RC
Morton Ranch High School	HS	Mounted Smartboards in all rooms.	MRHS	2	T
Morton Ranch High School	HS	Resurface track	Athletics	2	RC
Morton Ranch High School	HS	Replace chalkboards with whiteboards.	MRHS	2	RC
Morton Ranch High School	HS	Batting cages need replacement.	MRHS	2017B	RC
Morton Ranch High School	HS	Provide for small garage attached to dugout.	MRHS	2017B	P
Morton Ranch High School	HS	Cafeteria/Gym - need to repaint old logos in gyms. (Walls and floor.)	MRHS	CAMPUS	RC
Morton Ranch High School	HS	Fuses are easily blown in Admin office since they are connected to staff lounge.	MRHS	WO	BI
Morton Ranch High School	HS	Provide for elevator lift in PAC.	MRHS	GOF	P
Morton Ranch High School	HS	Softball stadium sound system is poor and the scoreboard needs repair after every home game.	MRHS	2017B	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Morton Ranch High School	HS	Build "Hitters Eye" fence in center field of baseball- only district campus without one	Athletics	2017B	P
Morton Ranch High School	HS	Expand weightroom- large numbers in weight room creates a safety issue	Weightroom Expansion	2	G
Morton Ranch High School	HS	CTE kitchen upgrades	MRHS	GOF	
Morton Ranch High School	HS	Collaborative furniture	MRHS	1	
Morton Ranch High School	HS	Add a female dressing room/ restroom in the fieldhouse around training room- they do not have a female restroom in the fieldhouse (female trainers/ athletic students)	Weightroom Expansion	2	P
Morton Ranch High School	HS	Replace bleachers in gyms	Athletics	1	RC
Morton Ranch High School	HS	Irrigation system update- all gradd practice fields, baseball and softball. Convert all irrigation systems from "2 core" to "conventional wiring system".	Athletics	GOF	RC
Morton Ranch High School	HS	Replace athletic lockers	Athletics	2	RC
Morton Ranch High School	HS	8 new natatorium starting blocks	Athletics	2017B	P
Morton Ranch High School	HS	Replacement scoreboards	Athletics	2017B	RC
Morton Ranch High School	HS	Replace sound system in gym/competition facilities	Athletics	2017B	RC
Morton Ranch High School	HS	Softball/ baseball new backstop competition field netting. Foul balls are landing on people's head in the bleachers and surrounding area.	Athletics	2017B	
Morton Ranch High School	HS	Tennis court resurface	Athletics	2017B	RC
Morton Ranch High School	HS	Pool- change track lighting to LIGHTRUSS	Athletics	2017B	E
Morton Ranch High School	HS	Replace drinking fountains with ones that accommodate water bottles for refilling.	MRHS	GOF	P
Morton Ranch Junior High	JH	Add additional video cameras to the surveillance system - interior and exterior.	MRJH	2017B	LS
Morton Ranch Junior High	JH	Outside storage building for athletic equipment.	Athletics	2014B	P
Morton Ranch Junior High	JH	Walk-in cooler/freezer replacement.	M&O	2	RC
Morton Ranch Junior High	JH	Gearboss system for athletic storage.	Athletics	2	P
Morton Ranch Junior High	JH	A traffic study needs to be completed for the MRHS, MRJH, and MRE compound to better meet the safety needs of our kids.	MRJH	2017B	G
Morton Ranch Junior High	JH	Resurface track.	Athletics	1	RC
Morton Ranch Junior High	JH	Lighted walkway awning from gym to parking lot. (Similar to SLJH.)	Athletics	2	SS
Morton Ranch Junior High	JH	Outside lighting on north side of the gym.	Athletics	2	SS
Morton Ranch Junior High	JH	Replace bleachers in gyms	MRJH	2	RC
Morton Ranch Junior High	JH	Replace athletic lockers	MRJH	2	RC
Morton Ranch Junior High	JH	Replacement scoreboards	MRJH	2017B	RC
Morton Ranch Junior High	JH	Replace sound system in gym/ competition facilities	MRJH	2017B	RC
Morton Ranch Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	MRJH	2	

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Morton Ranch Junior High	JH	Tennis court resurface	MRJH	2	RC
Morton Ranch Junior High	JH	30x30 concrete slab outside of weight room- new JH campuses are getting an extra concrete workout area outside of the weightroom area for workout space.	Weightroom Expansion	2	P
Morton Ranch Junior High	JH	Foundational cracks throughout the building; sinking areas in the floor in many areas of the building	MRJH	GOF	BI
Morton Ranch Junior High	JH	Exterior- no parking curbs on the front row of the staff parking spaces, which allows people to pull ahead in ongoing traffic	MRJH	2017B	SS
Morton Ranch Junior High	JH	chalkboards in all classrooms need to be replaced with dry erase boards	MRJH	2	P
Morton Ranch Junior High	JH	Locks in boys locker room need to be updated	MRJH	2	RC
Morton Ranch Junior High	JH	Athletic room- additional space is needed. With the stationary equipment, there is limited space for the students lift free weights to move freely through the weight room	MRJH	2	P
Morton Ranch Junior High	JH	White boards are needed in the LGI	MRJH	2	P
Nottingham Country Elementary	ELEM	All classroom doors need to be replaced with the push bar/ lever handle type so they will open "in" for safety	NCE	2014B	SS
Nottingham Country Elementary	ELEM	Frequent maintenance requests for exterior doors not latching properly	NCE	2017B	SS
Nottingham Country Elementary	ELEM	Gym/Cafeteria lights need replacing	NCE	1	E
Nottingham Country Elementary	ELEM	Hand washing stations need to be replaced. They either overshoot or wont stay on long enough or stay on too long	NCE	GOF	RC
Nottingham Country Elementary	ELEM	Whiteboards are needed to replace ancient chalkboards throughout building	NCE	GOF	RC
Nottingham Country Elementary	ELEM	Front foyer needs new tile	NCE	2014B	RC
Nottingham Country Elementary	ELEM	We have medically fragile unit on campus; therefore we really need a handicap entrance (automatic doors)	NCE	GOF	P
Nottingham Country Elementary	ELEM	The front offic/admin hallway needs new buil-in mailboxes. We have grown and do not have enough mail boxes for all staff	NCE	2	G
Nottingham Country Elementary	ELEM	Cafeteria/Gym- both need new flooring (we think we are scheduled to get this 2017-18)	NCE	2014B	RC
Nottingham Country Elementary	ELEM	Fine Arts- Room H and Room 64 need new tile flooring	NCE	2014B	RC
Nottingham Country Elementary	ELEM	The entire interior campus needs to be painted	NCE	GOF	RC
Nottingham Country Elementary	ELEM	The exterior of the building needs to be pressure washed and the poles and lettering on the building needs a fresh coat of paint	NCE	GOF	RC
Nottingham Country Elementary	ELEM	Playground shade structure.	M&O	2014B	SS
Nottingham Country Elementary	ELEM	Need LGI	NCE	2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Nottingham Country Elementary	ELEM	Potential library redesign to enclose	NCE	2	P
Nottingham Country Elementary	ELEM	Remove old existing boiler and tie existing lines into new.	2010	GOF	RC
Nottingham Country Elementary	ELEM	Replace chalkboards with whiteboards.	2010	GOF	RC
Nottingham Country Elementary	ELEM	Separate channels for the sound system in the .	2010	2	RC
Nottingham Country Elementary	ELEM	New updated sinks.	NCE	2	RC
Nottingham Country Elementary	ELEM	Tint Cafeteria & YCAP windows.	NCE	2	P
Nottingham Country Elementary	ELEM	Mulch frequently low.	NCE	WO	RC
Nottingham Country Elementary	ELEM	Extend covered walkway	2010	2	BI
Nottingham Country Elementary	ELEM	Replace exterior doors	NCE	2	RC
Nottingham Country Elementary	ELEM	Traffic Safety- reconfigure the driveways to allow better stacking of parents.	Emergency Management	2	G
Nottingham Country Elementary	ELEM	Security- reconfigure the main entrance to eliminate the sliding glass window and improve security.	Emergency Management	2017B	SS
Nottingham Country Elementary	ELEM	Security- install doors to isolate classroom spaces-in particular the classrooms for special education and for kindergarten.	Emergency Management	2	SS
OAC	HS	Need additional security cameras which will require another server. We have several key areas unmonitored.	OAC/RHS	2017B	LS
OAC	HS	Walk-in cooler/freezer replacement.	M&O	2	RC
OAC	HS	Additional classrooms in the future as BTP and RHS continue to grow - possibly future building addition.	OAC/RHS	2017B	G
OAC	HS	Remove the garage doors and double doors from classrooms 1033, 1036, 1049, and 1052 and replace with walls or doors that are insulated. During extreme temperature change these rooms are difficult to maintain standard air temp.	OAC/RHS	2017B	BI
OAC	HS	Carpet replacement.	M&O	2017B	RC
OAC	HS	One intercom and bell system for 3 different schools is disruptive to the learning environment.	OAC/RHS	2017B	
Outdoor Learning Center	OPER	Expansion and/or modifications to support curriculum.	Admin	2017B	G
Pattison Elementary	ELEM	Roof replacement.	M&O	2017B	RC
Pattison Elementary	ELEM	Parking lot lighting upgrade	PE	2017B	RC
Pattison Elementary	ELEM	Traffic Safety- reconfigure the western driveway to make it more usable as a parent stacking location.	Emergency Management	2	G
Pattison Elementary	ELEM	An additional serving line in the café for increase in student enrollment	Food Ser	2014B	G
Pattison Elementary	ELEM	change to new serving lines to the open concept; including frost top on the serving lines.The frost top ensures we can meet new health dept standards for keeping cold foods cold	Food Ser	2014B	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Pattison Elementary	ELEM	walk in freezer and cooler is warped on the inside and outside walls	Food Ser	2014B	RC
Print shop	Support	Additional space for equipment, at the Katy ISD Print Shop. Would like to request that we have approximately twice the current floor space, which would allow us to redesign the production floor, adding additional equipment and maximizing production work		GOF	P
Print shop	Support	additional space for personnel-Office space redesign		2	G
Print shop	Support	Additional space for storage of supplies & completed jobs		2	P
Randolph Elementary	ELEM	Need 2nd computer lab	JRE	3	P
Randolph Elementary	ELEM	Erosion corrections	JRW	GOF	RC
Rhoads Elementary	ELEM	Exterior portables need access into main building with security at doors - perhaps scanning system would be beneficial.	RES	2017B	LS
Rhoads Elementary	ELEM	Walk-in cooler/freezer replacement.	M&O	2	RC
Rhoads Elementary	ELEM	Replace carpet.	2010	2017B	RC
Rhoads Elementary	ELEM	Modify north drive to accommodate bus loading and parking lot to allow car rider stacking.	Safety	2017B	P
Rhoads Elementary	ELEM	Gym/Cafeteria flooring replacement.	M&O	2017B	RC
Rhoads Elementary	ELEM	Traffic Safety- reconfigure the front drive to reduce the stacking of car-rider vehicles on Clay Road reducing the risk of traffic accidents and improving the efficiency of arrival and dismissal.	Emergency Management	2017B	G
Rhoads Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
Rhoads Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Rhoads Elementary	ELEM	Security- relocate the west wall/gate of the mechanical yard to east of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Rhoads Elementary	ELEM	New gym floor	RES	2017B	RC
Rhoads Elementary	ELEM	Upgrade serving lines add cold/ frost tops-upgrade to KISD standards. Meet menu and health dept. requirements	Food Ser	2	P
Rhodes Stadium	Support	Add parking spaces to the northeast lot	M&O	2017B	P
Rhodes Stadium	Support	Replace roll down windows (5) with stainless steel	M&O	2	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Rhodes Stadium	Support	Add metal building for main equipment and chemical storage	M&O	GOF	P
Rhodes Stadium	Support	Resurface drive around stadium	M&O	2017B	RC
Rhodes Stadium	Support	Add bleachers at the south end zone to enhance crowd control and spectator safety		2	P
Rhodes Stadium	Support	Provide for canopy and power at filming area on Visitor side		2	P
Rhodes Stadium	Support	Replace turf fields and add E-Layer at all competition fields		2017B	RC
Rhodes Stadium	Support	All four stands need new refrigerators-very old and small. Need to keep product up to correct temp (health dept)	Food Ser	GOF	RC
Rhodes Stadium	Support	outlets- new and additional plugs. Not enough plugs needed for stadium use some don't work	Food Ser	GOF	P
Rhodes Stadium	Support	roll up windows-very hard to open, have had several accidents and also workman's comp	Food Ser	GOF	SS
Rhodes Stadium	Support	three compartment sink-we only have a 2 compartment sink- this is a requirement by Health Dept	Food Ser	2	P
Rhodes Stadium	Support	cooling units-we have none- only have barrels that need to be iced down	Food Ser	2	P
Rhodes Stadium	Support	Warmers-need proper warming units. Old warmers the schools had once used. Drawers missing, cant close and open drawers easily. Hard to keep temperature controlled	Food Ser	2	P
Rhodes Stadium	Support	Fans-need to be replaced- no air conditioned	Food Ser	GOF	RC
Rhodes Stadium	Support	Shelving-hard to keep food and disposables store properly	Food Ser	2	P
Rhodes Stadium	Support	No mop sink area- required by Health Dept.	Food Ser	2	P
(former) LD Robinson Pavilion	Support	Expansion for future program growth		TIRZ	G
RSC/STEAM	Support	additional storage addition-the RSC was built with limited storage. Currently we are using work areas for storage		3	G
RSC/STEAM	Support	parking issues need to be addressed. Interoffice mail vehicles and additional print shop staff leave no parking for vendors and/or staff needing to meet with purchasing dept. Need visitor spaces and additional parking in back of building for print shop.		3	G
RSC/STEAM	Support	We need to expand the RSC by adding 4 work bays to accommodate both robotics programs on nights and weekends and STEAM educationa ctivities during the day, at night and on weekends, additional bays are needed		3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Rylander Elementary	ELEM	Security- relocate the east wall/gate of the mechanical yard to west of the kitchen doors so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Rylander Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Rylander Elementary	ELEM	Playground-erosion has left several areas that are uneven (deep holes)- significant issue	RRE	WO	BI
Rylander Elementary	ELEM	Replace carpet.	2010	2017B	RC
Rylander Elementary	ELEM	Walk-in cooler/freezer replacement.	M&O	2	RC
Rylander Elementary	ELEM	Fine Arts/ Music - closet in room is too small since closet on stage is not being used by music department, but as school storage. Risers have to be stored on the stage. There is not enough room to store props and costumes in music room closets.	Fine Arts	3	P
Rylander Elementary	ELEM	No grass - are there any alternatives available for play surfaces?	RRE	GOF	
Rylander Elementary	ELEM	Extend covered walkway	2010	2	
Rylander Elementary	ELEM	Traffic Safety- create a cutout turn lane on Falcon Landing to allow school traffic to be outside the main flow of traffic and increase visibility for vehicles leaving the school parking lot; this will also make it more safe for students walking to school.	Emergency Management	2	SS
Rylander Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
Rylander Elementary	ELEM	Playground floods due to new construction	RRE	WO	BI
Rylander Elementary	ELEM	Additional classroom space	RRE	3	G
Schmalz Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
Schmalz Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Schmalz Elementary	ELEM	Need more storage	SES	1	P
Schmalz Elementary	ELEM	Custodians would like a light out by the playground or portables. When they go out to lock up at night it is very dark	SES	WO	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Schmalz Elementary	ELEM	Basketball court- water does not drain- standing water on it that creates hazard for mosquitos. Water has washed away the ground/ soil that stabilizes the tether ball poles.	SES	GOF	BI
Schmalz Elementary	ELEM	Teachers have requested that we be able to add equipment and structures at playground to give students more options for recess.	SES	2014B	P
Schmalz Elementary	ELEM	Gen/FA/intercom replacement.	M&O	1	RC
Schmalz Elementary	ELEM	Cafeteria/gym - mounted projector for assemblies, programs, and PE.	SES	2	T
Schmalz Elementary	ELEM	Walk-in cooler freezer replacement.	M&O	3	RC
Schmalz Elementary	ELEM	Chiller replacement.	M&O	2017B	RC
Schmalz Elementary	ELEM	Sink in the office area.	SES	2	P
Schmalz Elementary	ELEM	Roof replacement.	M&O	1	RC
Schmalz Elementary	ELEM	Remove vinyl on outside walls.	2010	3	BI
Schmalz Elementary	ELEM	Traffic Safety- create a cutout turn lane on Green Lane Way to allow traffic to flow in and out of the neighborhood during arrival and dismissal. This will make it more safe for students walking/bicycling to school.	Emergency Management	2017B	SS
Schmalz Elementary	ELEM	Security- relocate the north wall/gate of the mechanical yard to south of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Seven Lakes High School	HS	We do not have enough security cameras and the cameras we have are not good quality. There are dozens of areas throughout the building that are not covered by security cameras, leaving many areas unsecured	SLHS	2017B	LS
Seven Lakes High School	HS	Libraries - two additional security cameras and additional floor outlets in the storage room; much needed due to additional computer/iPad carts that are now necessary in high school libraries	SLHS	2	T
Seven Lakes High School	HS	Walk in Floral Cooler	CTE	2017B	P
Seven Lakes High School	HS	Flooring replacement (ceramic)	M&O	1	RC
Seven Lakes High School	HS	Enclosure of cafeteria commons	SLHS	3	P
Seven Lakes High School	HS	Additional restrooms and cooking space for life skills	SLHS	2	P
Seven Lakes High School	HS	Replace turf at competition field.	Athletics	2017B	RC
Seven Lakes High School	HS	Turf training area: Area with turf closer to the field house in the locating near the portables. This could be used for most sports.	SLHS	GOF	P
Seven Lakes High School	HS	Creating a doorway from 2274 to office allowing the teacher to move to and from his office/materials without passing through another classroom.	SLHS	3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Seven Lakes High School	HS	Locker rooms - 1. There is not enough locker room space for the number of athletes in programs throughout the building. This affects ALL sports - major Title IX concerns. 2. Expand the football locker rooms and weight room by eliminating the meeting rooms in the field house (1825). 3. Use area between the field house and main building to create more space for locker rooms/storage.	SLHS	3	G
Seven Lakes High School	HS	Remove classroom divider curtain in 1702A/B. Create additional weight room and training area for athletics. Our facilities are now too small to accommodate all of our student athletes.	SLHS	GOF	G
Seven Lakes High School	HS	Renovate the old darkroom in 1257 by removing darkroom door and add new lighting. Darkroom is now obsolete as a result of digital photography. This would allow for more storage in that area of the building.	SLHS	GOF	P
Seven Lakes High School	HS	Expansion of field house, weight room and coaches' offices.	Athletics	3	G
Seven Lakes High School	HS	Expansion of varsity locker room.	Athletics	3	G
Seven Lakes High School	HS	Create an additional driveway (street access) in the competition gym parking lot that will allow cars to enter and exit the competition gym parking lot quickly and safely. 2. A traffic light would be very helpful in front of the building-to manage traffic and protect student walkers.	SLHS	2017B	
Seven Lakes High School	HS	Replace bleachers in gyms	Athletics	1	RC
Seven Lakes High School	HS	Irrigation system update- all grass practice fields, baseball and softball. Convert all irrigation systems from "2 core" to "conventional wiring systems".	Athletics	GOF	RC
Seven Lakes High School	HS	Replace athletic lockers	Athletics	3	RC
Seven Lakes High School	HS	8 new natatorium starting blocks	Athletics	2017B	P
Seven Lakes High School	HS	Tennis court resurface	Athletics	2017B	RC
Seven Lakes High School	HS	Softball/baseball new backstop competition field netting. Foul balls are landing on people's head in the bleachers and surrounding areas.	Athletics	2017B	
Seven Lakes High School	HS	Baseball practice field redone and irrigation- need second field to practice.	Athletics	2017B	
Seven Lakes High School	HS	MAIN GYM relocate clock/AC/microphone main gym floor plugs (all gym sports)- safety of athletes when using practice courts for volleyball/basketball.	Athletics	3	BI

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Seven Lakes High School	HS	MAIN GYM retrofit main gym scoreboards to wireless controllers(all gym sports)- reliability of use for all gym sports for contest and daily use.	Athletics	3	BI
Seven Lakes High School	HS	Track- new shot put ring by the competition discus ring- existing shot put rings are too slick for competition use, when wet it's not safe.	Athletics	GOF	RC
Seven Lakes High School	HS	Pool- change track lighting to LIGHTRUSS	Athletics	2017B	E
Seven Lakes High School	HS	Football coaches dressing room expansion- since school opened we have a larger program and more staff. Need larger dressing room.	Weightroom Expansion	3	G
Seven Lakes High School	HS	ALL SPORTS expand weight room- due to larger athletic programs need more space.	Weightroom Expansion	3	G
Seven Lakes High School	HS	Need a new computer lab for new CTE course	SLHS	3	P
Seven Lakes High School	HS	Room 2302/2304 there is a crack in the floor that extends the length of the textbook room	SLHS	GOF	BI
Seven Lakes High School	HS	Carpet outside rooms 1312, 1313, 1315, and 1316 (Ag rooms) needs to be replaced due to wear and tear going in and out of the Ag workshops	SLHS	2017B	RC
	JH	Need a swipe system or bell system to open the back doors of the rotunda for students in the T-buildings.	SLJH	2017B	SS
Seven Lakes Junior High	JH	Resurface track.	Athletics	1	RC
Seven Lakes Junior High	JH	Do not have enough lockers to accommodate all of our students who want lockers.	SLJH	3	G
Seven Lakes Junior High	JH	Do not have enough PE and athletic lockers to accommodate our students.	SLJH	3	G
Seven Lakes Junior High	JH	Four additional math classrooms equipped with smartboards.	SLJH	3	G
Seven Lakes Junior High	JH	Four additional science classrooms equipped with smartboard, science.	SLJH	3	G
Seven Lakes Junior High	JH	Four additional T-buildings to house Social Studies, ELA, Spanish, and Art.	SLJH	GOF	G
Seven Lakes Junior High	JH	Need additional storage space for athletic equipment. We have close to 300 students on our football team. That is lots of pads, etc. that need to be stored.	SLJH	3	G
Seven Lakes Junior High	JH	Need additional water cows. Our athletes work in extreme heat and we can't keep up with their need for water.	SLJH	CAMPUS	G
Seven Lakes Junior High	JH	Need more storage space in orchestra room to accommodate all of the instruments.	SLJH	3	G
Seven Lakes Junior High	JH	One additional classroom for music instruction.	SLJH	3	G

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Seven Lakes Junior High	JH	Removal of gates and replaced with fence. To many points of entrance	Athletics	2017B	SS
Seven Lakes Junior High	JH	Shade Structures- covered area with electrical at entrance to FB field	Athletics	3	
Seven Lakes Junior High	JH	Tennis court resurface	Athletics	3	RC
Seven Lakes Junior High	JH	Placement of a garage door to access the outside space to accommodate additional athletes in the weight room workouts	Weightroom Expansion	3	P
Seven Lakes Junior High	JH	Pour a sidewalk from the gym foyer to the track entrance to avoid sand/dirt being tracked into the gym)	Weightroom Expansion	3	
Seven Lakes Junior High	JH	Additional computer lab	SLJH	3	P
Seven Lakes Junior High	JH	Motor lab for life skills	SLJH	3	P
Seven Lakes Junior High	JH	Restorative center	SLJH	3	P
Seven Lakes Junior High	JH	Full family and Consumer Science classroom	SLJH	3	P
Seven Lakes Junior High	JH	Science labs	SLJH	3	P
Seven Lakes Junior High	JH	Storage space	SLJH	3	P
Seven Lakes Junior High	JH	covered front walkway	SLJH	3	
Seven Lakes Junior High	JH	Unsecured entry doors due to the portable buildings	SLJH	3	SS
Seven Lakes Junior High	JH	Locker rooms would benefit from the addition of mounted TV's for announcements	SLJH	3	P
Seven Lakes Junior High	JH	Lockers in PE and Athletics are starting to break due to normal wear and tear	SLJH	3	RC
Seven Lakes Junior High	JH	More outlets are needed in the rear storage closet of the library	SLJH	GOF	P
Shafer Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Shafer Elementary	ELEM	Security- Relocate the south wall of the mechanical yard to north of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
South Transportation	Support	Netting and bollards for oil pits; for bird deterrent,	South Trans	2	G
South Transportation	Support	Electrical receptacles various locations	South Trans	GOF	G
South Transportation	Support	Light & gate by daycare	South Trans	2	G
South Transportation	Support	Dishwashers in daycare & room 219	South Trans	2	G
Special Education Facility	Support	Facility for high risk special education students	Special Education	UNDER REVIEW	P
Stanley Elementary	ELEM	Carpet replacement.	M&O	2	RC
Stanley Elementary	ELEM	Parent requests have been made to widen the front sidewalk.	SSE	2	
Stanley Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Stanley Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Stanley Elementary	ELEM	Security- relocate the north wall/gate of the mechanical yard to south of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Stanley Elementary		The teachers lounge could use a second fridge, however, there is not enough power in that room to run two of them	SSE	GOF	P
Stephens Elementary	ELEM	Playground shade structure.	M&O	2014B	SS
Stephens Elementary	ELEM	Gym/Cafeteria flooring and carpet replacement.	M&O	1	RC
Stephens Elementary	ELEM	Walk-in cooler/freezer replacement.	M&O	3	RC
Stephens Elementary	ELEM	There is no way to lock the partition doors that are between the gym/cafeteria and the gym/stage. Safety issue.	USE	WO	SS
Stephens Elementary	ELEM	No grass on playground - never has been.	USE	GOF	BI
Stephens Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
Stephens Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Stephens Elementary	ELEM	Room dividers to accommodate special programs	USE	2	P
Stephens Elementary	ELEM	Replacement of chalk boards with white boards	USE	2	P
Stephens Elementary	ELEM	Additional storage	USE	2	P
Stephens Elementary	ELEM	Replace playground equipment	USE	2014B	RC
Stephens Elementary	ELEM	Updated library furniture	USE	2	RC
Stephens Elementary	ELEM	Lighting adjustments for special education	USE	GOF	P
Stephens Elementary	ELEM	Security- relocate the east wall/gate of the mechanical yard to west of the kitchen doors so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day.	Emergency Management	2	SS
Sundown Elementary	ELEM	Playground shade structure.	M&O	2014B	SS
Sundown Elementary	ELEM	Upgrade playground equipment	SE	2017B	RC
Sundown Elementary	ELEM	Library - enclose. Open concept now exists and is difficult for librarian's lessons due to noise.	SE	2	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Sundown Elementary	ELEM	Need shelving in locker rooms. Rooms are no longer used for students. More storage is needed in PE equipment.	SE	2	P
Sundown Elementary	ELEM	Toilets, water fountains and urinals in the original building are old and in need of replacement.	2010	GOF	RC
Sundown Elementary	ELEM	Will need additional classroom space due to new apartment complex being built on Park Row Blvd.	SE	2	G
Sundown Elementary	ELEM	Enclose library	SE	2	P
Sundown Elementary	ELEM	Replace carpet.	2010	1	RC
Sundown Elementary	ELEM	Due to expanded "growth" next year, partitions are needed in the following classrooms - 400, 401, 402, 404, 500, 501, 502, 713, to accommodate Compensatory Ed, Dyslexia, and Title 1 teachers. This will allow us to place 2 supplemental intervention teachers in one room and free up space.	SE	2	G
Sundown Elementary	ELEM	Flood Foundation Stabilization-engineering study to determine if addition of a retaining wall on the north side of the school would be beneficial in creating a more flood resistant and stable soil condition. The retaining wall would also allow for additional space for accessible emergency egress on the north and northeast sides of the school.	Emergency Management	GOF	BI
Sundown Elementary	ELEM	General Safety- eliminate the dead-end hall on the northwest section of the classroom area.	Emergency Management	UNDER REVIEW	SS
Sundown Elementary	ELEM	Security- install or modify doors from the main north-south hall into the classroom areas with access control to isolate classrooms from intruders. Three sets of doors identified as needed for this.	Emergency Management	2	SS
Sundown Elementary	ELEM	Playground area is on sloop, continually washes away and gets ruts with rain	SE	GOF	BI
Sundown Elementary	ELEM	All main hallway doors need either hardware replacement or new doors	SE	2	RC
Sundown Elementary	ELEM	Offices/Teacher Lounge- Dishwasher needs replacing	SE	GOF	RC
Sundown Elementary	ELEM	Cafeteria/Gym - need updated PA system- unable to purchase wireless mics for the current equipment	SE	2	RC
Sundown Elementary	ELEM	Interior lighting upgrade	SE	1	RC
Sundown Elementary	ELEM	Janitorial rooms need updating	SE	2	P
James E. Taylor High School	HS	Replace turf	Athletics	2017B	RC
James E. Taylor High School	HS	9th grade central hall light inadequate- upgrade of fixtures needed	JTHS	2	RC
James E. Taylor High School	HS	Cabinet and door locks need replacement/upgrade	JTHS	3	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
James E. Taylor High School	HS	Covered sidewalks for 9th grade center-life skills students load in this area	JTHS	3	BI
James E. Taylor High School	HS	Drinking fountains for refilling water bottles/containers(including in the band hallway)	JTHS	3	BI
James E. Taylor High School	HS	Remove tennis/softball building-replace lockerrooms and office-building is falling apart due to age	Athletics	2017B	RC
James E. Taylor High School	HS	Add mat room in field house-space needed for safe instruction	Athletics	3	P
James E. Taylor High School	HS	Add turf area by Gym 3-more practice space needed	Athletics	3	P/G
James E. Taylor High School	HS	Renovate baseball coaches office-current office space inadequate	Athletics	3	P
James E. Taylor High School	HS	Hill and sand pits on practice fields-construction of a conditioning hill and sand pits	Athletics	CAMPUS	P
James E. Taylor High School	HS	New concession stand and restroom facility at competition field-original building on wrong side of the stadium	Athletics	3	P
James E. Taylor High School	HS	Pool- new deck	Athletics	2017B	BI
James E. Taylor High School	HS	Fence on football practice fields-fence not complete on the east side of the complex- safety/vandalism issue	Athletics	2017B	SS
James E. Taylor High School	HS	Multi purpose gym-provide space for outside sports on bad weather days	Athletics	3	P
James E. Taylor High School	HS	Add locker space in Field House-space needed for increased numbers	Athletics	3	G
James E. Taylor High School	HS	Replace bleachers in gyms	Athletics	3	RC
James E. Taylor High School	HS	Irrigation system update- all grass practice fields, baseball and softball. Convert all irrigation systems from "2 core" to "conventional wiring system".	Athletics	GOF	BI
James E. Taylor High School	HS	Replacement scoreboards	Athletics	2017B	RC
James E. Taylor High School	HS	Replace sound system in gym/competition facilities	Athletics	2017B	RC
James E. Taylor High School	HS	Tennis court resurface	Athletics	2017B	RC
James E. Taylor High School	HS	Upgrade serving lines: frost tops to keep cut fruits and vegetables at temp energy efficient milkcoolers-unrepairable Upgrade to meet KISD standards, meet menu and Health Dept. requirements	Food Ser	3	P
James E. Taylor High School	HS	Replace the roll down doors on serving line- poor airflow on serving line and lack of lighting	Food Ser	3	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
James E. Taylor High School	HS	Restrooms: front office restrooms- current men's room- replace urinal with toilet for conversion to women's restroom. Convert ladies restroom (single toilet) to men's room. Front office houses 7 women and 2 men. Changing restrooms would provide more equitable access	JTHS	3	P
James E. Taylor High School	HS	7-8 more welding stations are needed to accommodate demand. Need electrical outlets added to shop	JTHS	2	G
Tays Junior High	JH	Shade Structures- covered area with electrical at entrance to FB field	Athletics	2	
Tompkins High School	HS	Walk in Floral Cooler	CTE	2017B	P
Tompkins High School	HS	Resurface track.	Athletics	1	RC
Tompkins High School	HS	Pool- add showers behind diving well	Athletics	3	P
Tompkins High School	HS	Pool- install heat lamps behind diving well	Athletics	3	P
Tompkins High School	HS	Pool- pour concrete and build pavilion on backside of Natatorium	Athletics	3	P
Tompkins High School	HS	Tennis court resurface	Athletics	2017B	RC
Tompkins High School	HS	Replace turf fields and add E-Layer at all competition fields	Athletics	2	RC
Tompkins High School	HS	Additional drops/ electrical outlets in Comp classes above 31	OTHS	GOF	P
Tompkins High School	HS	Sidewalk access very limited for students walking or biking to campus, especially area in front of the Natatorium coming from Falcon Landing Blvd.	OTHS	GOF	SS
Warehouse	SUPPORT	In the previous ten years the district has opened 40 new campuses. If that growth rate continues over the next ten years, and responsibilities remain unchanged, then additional space will be needed for the main warehouse and textbook areas (areas marked #3 on "A" plan). Textbook area is already over capacity with one aisle of the main warehouse currently devoted to Textbook storage.	Warehouse	2	G
Warehouse	Support	Fixed Asset Storage area ("B" Plan) will need to be increased as well unless we take more surplus directly to the scrap yard or have public auctions every 30 to 60 days.		2	G
Warehouse	Support	Lighting in the Main Warehouse and textbook areas (marked #3 and #4 "A" Plan) is barely adequate. The light fixtures currently in use are old technology. A more modern lighting system would increase visibility and reduce the electricity bill.		2	E

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Warehouse	Support	Drive near docks 6-8 needs to be extended to the east so that semi delivery trucks can safely make deliveries. "A" plan 9b		2	SS
Warehouse	Support	large ruts are developing in the earth just outside the vehicle door on the south side of the Surplus Warehouse. Need the concrete extended or gravel/dirt mixture added to this space to fill these ruts. "B" plan 9d		2	BI
Warehouse	Support	Walk in doors for SERS and Assessment need and exterior rain cover and lighting to protect employees while they are unlocking the door. "A" plan 9E		2	
Warehouse	Support	We need to expand the RSC by adding 4 work bays to accommodate both robotics programs on nights and weekends and STEAM educationa ctivities during the day, at night and on weekends, additional bays are needed		2	P
West Memorial Elementary	ELEM	Walk in cooler freezer replacement	M&O	1	RC
West Memorial Elementary	ELEM	Close in open tiled area next to room 106.	WME	1	P
West Memorial Elementary	ELEM	Updating the "West Memorial Elementary" lettering would alleviate some of the community's negative comments and develop better community relations.	WME	1	RC
West Memorial Elementary	ELEM	Front office door needs buzzer to open from behind the counter by the office staff.	WME	2017B	SS
West Memorial Elementary	ELEM	Security lighting needed.	WME	2017B	SS
West Memorial Elementary	ELEM	General Safety- Create another exterior door to improve emergency egress.	Emergency Management	1	SS
West Memorial Elementary	ELEM	General Safety- add classrooms to reduce crowding.	Emergency Management	1	G
West Memorial Elementary	ELEM	Wing addition to the back of the school	WME	1	G
West Memorial Elementary	ELEM	Stucco the front of the school with the addition of an awning similar to WMJH	WME	1	
West Memorial Elementary	ELEM	Expansion of the cafeteria	WME	1	G
West Memorial Elementary	ELEM	Add awnings to the area by room 152 and the Pre K courtyard	WME	1	
West Memorial Elementary	ELEM	standing water in these areas: portables and blacktop areas, rear side walks	WME	GOF	BI
West Memorial Elementary	ELEM	Main key to enter all exterior doors for teachers	WME	2017B	SS
West Memorial Elementary	ELEM	radios and cell phones have limited access in the building	WME	GOF	
West Memorial Elementary	ELEM	take down the brick wall by the flagpole	WME	1	
West Memorial Elementary	ELEM	Additional lights need to be installed in these areas: portables, all playground areas, front and side areas to prevent vandalism.	WME	1	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
West Memorial Elementary	ELEM	Keys are an issue as staff members are having difficulty opening doors due to age of the key or the keyhole. Teachers need keys for cabinets and they are not available to hand out to the staff	WME	1	SS
West Memorial Elementary	ELEM	Heating and air conditioning have been an on-going problem for the past 5 years. They are not regulating adequately	WME	2017B	E
West Memorial Elementary	ELEM	Choir room: there are two choir rooms at WME which need shelving above the counter space so that instruments can be stored as there is no storage	WME	1	P
West Memorial Elementary	ELEM	Expand cafeteria into atrium	WME	1	P
West Memorial Elementary	ELEM	second serving line to increase in participation- allow students more time to eat lunch and less time standing in line	Food Ser	1	P
West Memorial Elementary	ELEM	upgrade serving lines-upgrade to kisd standards,meet menu and health dept. requirements - add cold/ frost tops -add water spouts to fill serving lines	Food Ser	1	P
West Memorial Elementary	ELEM	walk in cooler/freezer- replace and increase size-meet menu and health dept requirements	Food Ser	1	RC
West Memorial Elementary	ELEM	Addition of pass through warmer and cooler-safety issue when putting hot food in warming unit- must pass behind server	Food Ser	1	P
West Memorial Elementary	ELEM	Open up serving line to storefront- upgrade to KISD standards increase participation- meet customer needs	Food Ser	1	P
West Memorial Elementary	ELEM	Security- install or modify doors outside rooms B01 and B05 with access control to isolate classroom area from main hallway (the hall outside the cafeteria and gym)	Emergency Management	1	SS
West Memorial Junior High	JH	Additional security camera on back side of campus by T-buildings.	WMJH	2017B	SS
West Memorial Junior High	JH	Both gyms needs new bleachers and new frames for the backboards (main and side goals.)	WMJH	2017B (Bleachers)	RC
West Memorial Junior High	JH	Screen and projector needed in LGI.	WMJH	2	P
West Memorial Junior High	JH	Speaker system in LGI.	WM	2	P
West Memorial Junior High	JH	Gearboss system for athletic storage.	Athletics	3	P
West Memorial Junior High	JH	New scoreboards are needed for both gyms.	Athletics	3	RC
West Memorial Junior High	JH	Resurface track.	Athletics	1	
West Memorial Junior High	JH	Additional staff/visitor parking in front of campus, as well as additional parking behind our cafeteria for cafeteria staff.	WMJH	3	G
West Memorial Junior High	JH	New fence around football field/track. Vandalism-safety of equipment	Athletics	2017B	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
West Memorial Junior High	JH	Shade Structures- covered area with electrical at entrance to FB field	Athletics	3	
West Memorial Junior High	JH	Tennis court resurface	Athletics	2017B	RC
West Memorial Junior High	JH	Additional sinks to support science	WMJH	3	P
West Memorial Junior High	JH	Additional serving line in cafeteria	WMJH	3	G
West Memorial Junior High	JH	The parking has not adequately served this facility. Need additional parking in the front parking lot. Patrons and staff are usually parking on the grass	WMJH	3	G
West Transportation	OPER	Electronic gates tend to malfunction after rain/electrical storms.	W TRAN	2017B	BI
West Transportation	OPER	Facility camera system - old system not functional.	W TRAN	2017B	SS
West Transportation	OPER	Ice machine in the drivers' lounge is in need of replacement.	W TRAN	GOF	RC
West Transportation	OPER	Parking lot access signs - no signs limiting access at this time.	W TRAN	GOF	P
West Transportation	OPER	Parking area continues to have sunken area at expansion joints in concrete. This includes the access road off of Katy Hockley Cut Off Road.	W TRAN	2017B	BI
West Transportation	OPER	Replace carpet.	M&O	2017B	RC
West Transportation	OPER	Chiller replacement.	M&O	2017B	RC
West Transportation	OPER	Administrative offices are direct access to anyone. No control over who may enter.	W TRAN	2017B	SS
West Transportation	OPER	Daycare has a drainage problem in the play ground.	W TRAN	2017B	BI
West Transportation	OPER	Larger office space- lead office has 2 employees in a 9x9 room	W TRAN	GOF	G
West Transportation	OPER	larger parking lot- not enough room for all employees	W TRAN	2	G
West Transportation	OPER	larger dispatch area	W TRAN	GOF	G
West Transportation	OPER	parking lot has cracks and large pot holes and concrete is uneven in many areas	W TRAN	2017B	BI
Williams Elementary	ELEM	Walk-in cooler/freezer replacement.	Food Ser	2	RC
Williams Elementary	ELEM	Chiller replacement.	M&O	2017B	RC
Williams Elementary	ELEM	Generator/Fire Alarm/ Intercom replacement.	M&O	2017B	RC
Williams Elementary	ELEM	Renovate art rooms and reconfigure Admin area including adding door in hallway outside principal's office, restrooms, clinic and teachers' lounge expansion.	2010	2	P
Williams Elementary	ELEM	Replace restroom floors with synthetic floor.	2010	2	RC
Williams Elementary	ELEM	Exterior maroon paint needs to be repainted on the roof, trim, doors, and rain gutters.	JWE	GOF	RC
Williams Elementary	ELEM	Library - Formica trim on the cabinets throughout the library is coming loose/falling off.	JWE	2	RC
Williams Elementary	ELEM	Stage steps need to be varnished.	JWE	2	RC

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Williams Elementary	ELEM	In need of new plumbing fixtures, soap dispensers, and paper towel dispensers in some of the restrooms.	JWE	2	RC
Williams Elementary	ELEM	Cover for playground area	JWE	2014B	
Williams Elementary	ELEM	Update PA system to accommodate USB cables,HDMI cables, phone, ipad, etc	JWE	GOF	RC
Williams Elementary	ELEM	Can we get filtered H2O stations like at the new High Schools (bottle fill stations)	JWE	2	P
Williams Elementary	ELEM	Office/ teacher lounge-new appliances- dishwasher, garbage disposals	JWE	2	RC
Williams Elementary	ELEM	Updated open concept serving line-update to KISD standards	JWE	2	P
Williams Elementary	ELEM	Addition of teacher planning rooms	JWE	2	P
Williams Elementary	ELEM	Additional classrooms and program support spaces to support programs	JWE	2	P
Williams Elementary	ELEM	LGI space as with current prototypes	JWE	2	P
Williams Elementary	ELEM	Additional conference rooms	JWE	2	P
Williams Elementary	ELEM	Security- install or modify doors and access control to isolate classroom spaces from the main hallway. On this basic floor plan there are seven corridors.	Emergency Management	2	SS
Wilson Elementary	ELEM	Double doors at the end of all grade level hallways (exit doors)	TWE	2	
Wilson Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Wilson Elementary	ELEM	Security- relocate the northeast wall of the mechanical yard to southwest of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that yard can be kept locked during the day.	Emergency Management	2	SS
Wilson Elementary	ELEM	Motor lab space	TWE	2	P
Winborn Elementary	ELEM	Building renovation	FCP	1	RC
Winborn Elementary	ELEM	Library - needs updating.	DWE	1	P
Winborn Elementary	ELEM	Chiller replacement.	M&O	2017B	RC
Winborn Elementary	ELEM	Covering for Special Education loading area.	DWE	1	BI
Winborn Elementary	ELEM	Cafeteria/Gym - No area to project for assemblies in there without a portable screen.	DWE	1	P
Winborn Elementary	ELEM	Carpet replacement.	DWE	1	RC
Winborn Elementary	ELEM	Safety & security - entrance is not secure once a person enters office.	DWE	2017B	SS

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
Winborn Elementary	ELEM	We have 3 life skills programs here. We do not have a restroom located in or around these programs. The life skills staff have to take all children out of the classroom and down the hallway to use the restroom and toilet train if it is indicated in a student's IEP	DWE	1	P
Winborn Elementary	ELEM	library update- built in 1981- doesn't reflect a current library needs for students	DWE	1	P
Winborn Elementary	ELEM	Air conditioner- inconsistency in temperature across the building	DWE	1	E
Winborn Elementary	ELEM	This building is in a plumbing crisis- flushing toilets are loud and pipes shake the walls; urinals are backed up; leaking around water fountains, toilets, and hand washing stations. When someone flushes the toilet the walls shake near the restroom. Water fountains are constantly breaking. Toilets are constantly leaking.	DWE	1	BI
Winborn Elementary	ELEM	Traffic flow in the neighborhood, drainage by portables	DWE	1	
Winborn Elementary	ELEM	Kitchen needs updating	DWE	1	P
Winborn Elementary	ELEM	Locker rooms- using as storage	DWE	1	P
Winborn Elementary	ELEM	New ovens (2 ovens=1 stack)-current stack of ovens are not working properly and causing more work for the staff to produce adequate meal items at a reasonable time	Food Ser	1	RC
Wolman Elementary	ELEM	Traffic Safety- install a pedestrian hybrid beacon that will allow students to cross South Firethorn at the flood control ditch hike and bike trail. This will be a direct benefit to the school by providing a safe location for students to cross.	Emergency Management	2	SS
Wolman Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
Wolman Elementary	ELEM	Security-relocate the north wall of the mechanical yard to south of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that the yard can be kept locked during the day	Emergency Management	2	SS
WoodCreek Elementary	ELEM	Gym/Cafeteria/carpet flooring replacement.	M&O	1	RC
WoodCreek Elementary	ELEM	More storage for furniture especially when grade levels are being changed.	2010	3	G

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
WoodCreek Elementary	ELEM	Need a concrete walkway outside where the busses line up around the curb. Currently kids walk on grass with ants and lots of mud. Some of the grass areas have holes that need to be filled in.	WCE	2	P
WoodCreek Elementary	ELEM	LGI - exterior door - facing north - blowing rain seeps down the door along facings and leaks into the room - wetting the carpet.	WCJH	GOF	BI
WoodCreek Elementary	ELEM	Requested a doorbell at front of building for summer hours - other schools have one.	WCE	2017B	P
WoodCreek Elementary	ELEM	Request TV monitor that showed security cameras.	WCE	2017B	SS
WoodCreek Elementary	ELEM	General Safety- create a door from the main hallway into the clinic to eliminate the need for students to enter the security vestibule to access the nurse.	Emergency Management	1	SS
WoodCreek Elementary	ELEM	Security- create doors to isolate special education and kindergarten classroom areas from the rest of the building for security-install access control on the doors.	Emergency Management	2	SS
WoodCreek Elementary	ELEM	Security- relocate the northeast wall of the mechanical yard to southwest of the kitchen door so that the kitchen staff does not have to enter the mechanical yard to access the kitchen and so that yard can be kept locked during the day.	Emergency Management	2	SS
WoodCreek Elementary	ELEM	Raise the concrete on bus dock. The concrete has low spots that puddle in rain. This is causing students and staff to have to walk through and stand in large puddles as they load the buses or get in their cars.	WCE	2	BI
WoodCreek Junior High	JH	Gearboss system for athletic storage.	Athletics	3	P
WoodCreek Junior High	JH	Restructure the weight room with double doors leading outside.	Athletics	3	P
WoodCreek Junior High	JH	Carpet replacement.	M&O	1	RC
WoodCreek Junior High	JH	Tile floor - surface creates a slipping-falling hazard when wet. With our many portable buildings all entrances are a concern. Campus add mats - staff stands at entrances with mops.	WCJH	GOF	RC
WoodCreek Junior High	JH	Replace existing locking mechanisms on lockers.	Athletics	3	RC
WoodCreek Junior High	JH	Add 19' x 30' concrete slab outside weight room- create outdoor space outside of weight room	Weightroom Expansion	3	P
WoodCreek Junior High	JH	Need more weight room space for the number of kids in the program	Weightroom Expansion	3	G
WoodCreek Junior High	JH	30x30 covered awning for concrete slab- create all weather outdoor space	Weightroom Expansion	3	P
WoodCreek Junior High	JH	Storage renovation install Gearboss- create more space with better storage system	Athletics	3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
WoodCreek Junior High	JH	Replace athletic lockers	Athletics	3	RC
WoodCreek Junior High	JH	Shade structures- covered area with electrical at entrance to FB field	Athletics	3	
WoodCreek Junior High	JH	Tennis court resurface	Athletics	2017B	RC
WoodCreek Junior High	JH	There are cracks in the cinder block walls due to foundation problems. 1.Main hallway between rooms 1195-1194- located in the front of the school 2. main hallway by gyms- a. west wall adjacent to the fire extinguisher b. west wall across from the trophy case c. weight room- wall under the dry erase board	WCJH	GOF	BI
WoodCreek Junior High	JH	Security cameras need to be fixed and or replaced. Work order input on 8/26/16 for 2 security cameras not working that still are not fixed. This creates a major security, safety concern.	WCJH	2017B	SS
WoodCreek Junior High	JH	Court yard area- this are needs to be concreted like SLJH and Tays JH. This area becomes a mud pit when it rains	WCJH	GOF	BI
WoodCreek Junior High	JH	Covered walkways are needed 1. front entrance sidewalk should be covered like Tays JH. Parents will only stop at the small section directly in front of the building to let student out. This would help the large car rider line to continue to flow efficiently 2. outside gym lobby- distance parents/staff/KISD buses must park away from the entrance creating slipping hazards	WCJH	3	
WoodCreek Junior High	JH	Administrative offices need to be reconfigured and relocated. Principals office/ secretary office need to be relocated to the end of the hallway-like Tays JH. Offices need to be resized to accommodate this building change. It is very hard to ensure confidentiality with conversations regarding students, conversations with parents as these offices are directly located in the front office.	WCJH	3	P

FACILITY NAME	FACILITY TYPE	DESCRIPTION	SOURCE	PLANNING PERIOD	RATIONALE
WoodCreek Junior High	JH	WCJH needs to have automatic water bottle filling machines installed in the athletic areas similar to those in the new Jr./Sr. High buildings	WCJH	3	P
WoodCreek Junior High	JH	Lack of storage for music stands, performance chairs, etc. continues to be a problem. WCJH has asked for permission to get "pods" to store this extra furniture etc. which has not been approved. Having this extra equipment creates hazards for students.	WCJH	3	P
WoodCreek Junior High	JH	WCJH needs to have a learning area created for classroom lessons in our library. Currently we have tables set up in the library and a screen which drops down blocking 2 computer lab doors. Constant traffic in the library interrupts learning process.	WCJH	3	P
WoodCreek Junior High	JH	Custodians do not have a location to store the large floor cleaning machine. The fire marshal has stated it does not need to be stored in the hallway near their office. We have band, orchestra students that many times cannot walk in the hall safely.	WCJH	GOF	P